

AD-A084 373

BAKER (MICHAEL) JR INC BEAVER PA

F/6 13/13

NATIONAL DAM SAFETY PROGRAM. SOUTH RIVER NUMBER 6 (ID VA-01509)--ETC(U)

FEB 80 J A WALSH

DACW65-78-D-0016


NL

UNCLASSIFIED

1 of 2

AD-A084 373

AD-A084 373



POTOMAC RIVER BASIN

Name of Dam: South River No. 6


Location: Augusta County, State of Virginia

Inventory Number: VA 01509

LEVEL

PHASE I INSPECTION REPORT
NATIONAL DAM SAFETY PROGRAM

ADA084373



DTIC
ECTE
MAY 21 1980

THIS DOCUMENT IS BEST QUALITY PRACTICABLE.
THE COPY FURNISHED IS NOT NEARLY A
SIGNIFICANT NUMBER OF PAGES WHICH DO NOT
REPRODUCE LEGITIMATELY.

PREPARED FOR

NORFOLK DISTRICT CORPS OF ENGINEERS
803 FRONT STREET
NORFOLK, VIRGINIA 23510

PREPARED BY

MICHAEL BAKER, JR., INC.
BEAVER, PENNSYLVANIA 15009

February 1980

This document has been approved
for public release and sale; its
distribution is unlimited.

80 5 19 032

DISCLAIMER NOTICE

**THIS DOCUMENT IS BEST QUALITY
PRACTICABLE. THE COPY FURNISHED
TO DTIC CONTAINED A SIGNIFICANT
NUMBER OF PAGES WHICH DO NOT
REPRODUCE LEGIBLY.**

SECURITY CLASSIFICATION OF THIS PAGE (When Data Entered)

REPORT DOCUMENTATION PAGE		READ INSTRUCTIONS BEFORE COMPLETING FORM
1. REPORT NUMBER VA 01509	2. GOVT ACCESSION NO. AD-A084373	3. RECIPIENT'S CATALOG NUMBER
4. TITLE (and Subtitle) Phase I Inspection Report National Dam Safety Program SOUTH RIVER NO. 6 AUGUSTA COUNTY, VA		5. TYPE OF REPORT & PERIOD COVERED (9) Final rept.
7. AUTHOR(s) Michael Baker, Jr., Inc. 4301 Dutch Ridge Road, Box 280 Beaver, Pennsylvania 15009		6. PERFORMING ORG. REPORT NUMBER
9. PERFORMING ORGANIZATION NAME AND ADDRESS (12) 966		8. CONTRACT OR GRANT NUMBER(s) DACW65-78-D-0016
11. CONTROLLING OFFICE NAME AND ADDRESS U.S. Army Engineering District, Norfolk 803 Front Street Norfolk, VA 23510		10. PROGRAM ELEMENT, PROJECT, TASK AREA & WORK UNIT NUMBERS
14. MONITORING AGENCY NAME & ADDRESS (if different from Controlling Office)		12. REPORT DATE (11) Feb 1980
		13. NUMBER OF PAGES
		15. SECURITY CLASS. (of this report) Unclassified
		15a. DECLASSIFICATION/DOWNGRADING SCHEDULE
16. DISTRIBUTION STATEMENT (of this Report) Approved for public release; distribution unlimited.		
17. DISTRIBUTION STATEMENT (of the abstract entered in Block 20, if different from Report)		
18. SUPPLEMENTARY NOTES Copies are obtainable from National Technical Information Service, Springfield, Virginia 22151		
19. KEY WORDS (Continue on reverse side if necessary and identify by block number) Dams - VA National Dam Safety Program Phase I Dam Safety Dam Inspection		
20. ABSTRACT (Continue on reverse side if necessary and identify by block number) (See reverse side) (6) National Dam Safety Program, South River Number 6 (ID VA-01509), Potomac River Basin, um... Cold Spring... Virginia ... = Inspection Report		

DD FORM 1473

1 JAN 73

EDITION OF 1 NOV 65 IS OBSOLETE

Unclassified 420722
SECURITY CLASSIFICATION OF THIS PAGE (When Data Entered)

20. Abstract

Pursuant to Public Law 92-367, Phase I Inspection Reports are prepared under guidance contained in the recommended guidelines for safety inspection of dams, published by the Office of Chief of Engineers, Washington, D. C. 20314. The purpose of a Phase I investigation is to identify expeditiously those dams which may pose hazards to human life or property. The assessment of the general conditions of the dam is based upon available data and visual inspections. Detailed investigation and analyses involving topographic mapping, subsurface investigations, testing, and detailed computational evaluations are beyond the scope of a Phase I investigation; however, the investigation is intended to identify any need for such studies.

Based upon the field conditions at the time of the field inspection and all available engineering data, the Phase I report addresses the hydraulic, hydrologic, geologic, geotechnic, and structural aspects of the dam. The engineering techniques employed give a reasonably accurate assessment of the conditions of the dam. It should be realized that certain engineering aspects cannot be fully analyzed during a Phase I inspection. Assessment and remedial measures in the report include the requirements of additional indepth study when necessary.

Phase I reports include project information of the dam and appurtenances, all existing engineering data, operational procedures, hydraulic/hydrologic data of the watershed, dam stability, visual inspection report and an assessment including required remedial measures.

PREFACE

This report is prepared under guidance contained in the Recommended Guidelines for Safety Inspection of Dams, for Phase I Investigations. Copies of these guidelines may be obtained from the Office of the Chief of Engineers, Washington, D.C. 20314. The purpose of a Phase I investigation is to identify expeditiously those dams which may pose hazards to human life or property. The assessment of the general condition of the dam is based upon available data and visual inspections. Detailed investigation and analyses involving topographic mapping, subsurface investigations testing, and detailed computational evaluations are beyond the scope of a Phase I investigation; however, the investigation is intended to identify any need for such studies.

In reviewing this report, it should be realized that the reported condition of the dam is based on observations of field conditions at the time of inspection along with data available to the inspection team. In cases where the reservoir was lowered or drained prior to inspection, such action, while improving the stability and safety of the dam, removes the normal load on the structure and may obscure certain conditions which might otherwise be detectable if inspected under the normal operating environment of the structure.

It is important to note that the condition of a dam depends on numerous and constantly changing internal and external conditions, and is evolutionary in nature. It would be incorrect to assume that the present condition of the dam will continue to represent the condition of the dam at some point in the future. Only through continued care and inspection can there be any chance that unsafe conditions be detected.

Phase I inspections are not intended to provide detailed hydrologic and hydraulic analyses. In accordance with the established guidelines, the spillway design flood is based on the estimated "Probable Maximum Flood" for the region (flood discharges that may be expected from the most severe combination of critical meteorologic and hydrologic conditions that are reasonably possible), or fractions thereof. Because of the magnitude and rarity of such a storm event, a finding that a spillway will not pass the design flood should not be interpreted as necessarily posing a highly inadequate condition. The design flood provides a measure of relative spillway capacity and serves as an aid in determining the need for more detailed hydrologic and hydraulic studies, considering the size of the dam, its general condition, and the downstream damage potential.

PHASE I INSPECTION REPORT NATIONAL DAM SAFETY PROGRAM

CONTENTS

	<u>Page</u>
Preface.	i
Brief Assessment of Dam	1
Overall View of Dam	5
Section 1: Project Information	7
Section 2: Engineering Data	11
Section 3: Visual Inspection	13
Section 4: Operational Procedures	15
Section 5: Hydraulic/Hydrologic Data	17
Section 6: Dam Stability	21
Section 7: Assessment/Remedial Measures	23

Appendices

- I. Plates
- II. Photographs
- III. Visual Inspection Check List
- IV. Operation and Maintenance Inspection Report
- V. Excerpts from Geology Report
- VI. Design Report
- VII. Excerpts from Design Calculations
- VIII. General References

Accession For

WISCONSIN

DATE FEB

UNCLASSIFIED

Justification

BY

RECEIVED

Availability Cases

Dist A

Availability/or special

NAME OF DAM: SOUTH RIVER No. 6

PHASE 1 INSPECTION REPORT
NATIONAL DAM SAFETY PROGRAM

Name of Dam: South River No. 6
State: Virginia
County: Augusta
USGS 7.5 Minute Quadrangle: Big Levels, VA
Stream: Gum Springs Branch, Deep Pond Run, Cold Spring Branch
Date of Inspection: 14 November 1979

BRIEF ASSESSMENT OF DAM

South River No. 6 dam is an earthfill dam with an embankment approximately 910 feet long and 56 feet high, and a 175 foot wide vegetated earth emergency spillway. The dam, located approximately 2.2 miles south of Greenville, Virginia, is used for flood control and recreation. The dam is owned by Mr. David Willingham. South River No. 6 dam is an "intermediate" size - "high" hazard structure as defined by the Recommended Guidelines for Safety Inspection of Dams. Visual inspection and office analyses indicate no deficiencies requiring emergency attention.

Using the Corps of Engineers screening criteria for initial review of spillway adequacy, the Probable Maximum Flood (PMF) was selected as the spillway design flood (SDF). The SDF was routed through the reservoir and found to overtop the dam by a maximum depth of 1.3 feet with an average critical velocity of 5.3 f.p.s. Total duration of dam overtopping would be approximately 3.0 hours. The emergency spillway is capable of passing only 60 percent of the PMF and is adjudged as inadequate, but not seriously inadequate.

The dam and appurtenant structures were found to be in generally good overall condition. No conditions indicating embankment instability were detected during the field inspection and office analyses.

A warning system should be installed to alert campers and downstream residents of rising water within the reservoir. The warning system should be approved by the state and by the local conservation district. An emergency action plan should also be developed.

It is recommended that the following repair items be accomplished as part of an annual maintenance program:

- 1) Fill the animal burrow below the toe on the right side of the embankment.

NAME OF DAM: SOUTH RIVER No. 6

- 2) Reseed the areas of sparse vegetation on the embankment.
- 3) Install a staff gage in the reservoir to monitor high water levels.

The owner should contact the local Soil and Water Conservation District about possible replacement or repair of the emergency drawdown head gate, which is operable but reportedly difficult to reseal.


The owner should also give serious consideration to relocating the campground office/store from the emergency spillway to an elevation higher than the dam crest.

Original signed by
JAMES A. WALSH


MICHAEL BAKER, JR., INC. SUBMITTED:

James A. Walsh, P.E.
Chief, Design Branch

Original Signed by:
Ronald G. Vann


Michael Baker, III, P.E.
Chairman of the Board and
Chief Executive Officer

RECOMMENDED:

 Jack G. Starr, P.E.
Chief, Engineering

Original signed by:
Douglas L. Haller

APPROVED:

Douglas L. Haller
Colonel, Corps of Engineers
District Engineer



MAR 14 1980

Date: _____

NAME OF DAM: SOUTH RIVER No. 6



OVERALL VIEW OF DAM

PRECEDING PAGE BLANK-NOT FILMED

PHASE I INSPECTION REPORT
NATIONAL DAM SAFETY PROGRAM
NAME OF DAM: SOUTH RIVER No. 6 ID #VA 01509

SECTION 1 - PROJECT INFORMATION

1.1 General

- 1.1.1 Authority: Public Law 92-367, 8 August 1972, authorized the Secretary of the Army, through the Corps of Engineers, to initiate a national program of safety inspections of dams throughout the United States. The Norfolk District has been assigned the responsibility of supervising the inspection of dams in the Commonwealth of Virginia.
- 1.1.2 Purpose of Inspection: The purpose is to conduct a Phase I inspection according to the Recommended Guideline for Safety Inspection of Dams. The main responsibility is to expeditiously identify those dams which may be a potential hazard to human life or property.

1.2 Description of Project

- 1.2.1 Description of Dam and Appurtenances: South River No. 6 dam, a flood control dam designed by the U.S. Department of Agriculture, Soil Conservation Service (SCS), is also known by its local name, Senger's Mountain Lake. The earthfill embankment is approximately 56 feet high¹ and 910 feet long. The embankment has side slopes of 2.5H:1V (Horizontal to Vertical) and 3H:1V on the downstream and upstream faces respectively. There is a 10 feet wide berm on the downstream face of the embankment at elevation 1616.25 feet Mean Sea Level (M.S.L.) Seepage control is provided by an impervious core, a cut-off trench, and a seepage drain. The seepage drain is located approximately 112 feet from the downstream toe of the dam and consists of a filter and a 6 inch perforated bituminous coated corrugated metal pipe. The drain system exits through a single 6 inch unperforated bituminous coated corrugated metal pipe, immediately to the left of the principal outlet pipe, into the stilling basin.

¹Measured from invert of outlet pipe to crest of dam.

NAME OF DAM: SOUTH RIVER No. 6

The principal spillway is a fixed crest (elevation 1601.5 feet M.S.L) drop inlet structure consisting of a reinforced concrete riser approximately 11 feet high with a 24 inch diameter reinforced concrete outlet pipe. The outlet pipe is 337 feet long and is fitted with 8 reinforced concrete anti-seep collars on 24 foot centers as it passes through the embankment. The outlet discharges into a riprap-lined and tapered 12 feet wide and 20 feet long stilling basin. The basin has side slopes of 1:1 and a level bottom.

The emergency spillway, a 175 feet wide vegetated earth channel, is located outside the left abutment of the dam. The approach channel of the emergency spillway rises at a slope of 3 percent to the control section at elevation 1635.0 feet M.S.L. A campground office/store is constructed in the approach channel. Beyond the 20 foot long control section the discharge channel slope is 3 percent.

The emergency drawdown valve, located on the principal spillway riser, is a 24 inch circular head gate controlled by a handwheel lift mechanism located on top of the riser platform.

- 1.2.2 Location: South River No. 6 dam is located on Cold Spring Branch approximately 2.2 miles southeast of Greenville, Augusta County, Virginia. A Location Plan is included with this report.
- 1.2.3 Size Classification: The maximum height of the dam is 53 feet; the reservoir storage capacity at the crest of the dam (elevation 1642.0 feet M.S.L.) is 1263 acre-feet. Therefore the dam is in the "intermediate" size category as defined by the Recommended Guidelines for Safety Inspection of Dams.
- 1.2.4 Hazard Classification: Within 1 mile downstream of the dam are 3 permanent residential structures and 2 mobile homes. The permanent structures are constructed on relatively high ground while the mobile homes are in a low-lying area. Loss of life is highly probable along with economic losses. South River No. 6 dam is therefore considered in the "high" hazard

NAME OF DAM: SOUTH RIVER No. 6

category as defined by the Recommended Guidelines for Safety Inspection of Dams. The hazard classification used to categorize dams is a function of location only and has nothing to do with its stability or probability of failure.

1.2.5 Ownership: The dam is owned by Mr. David Willingham, Senger's Mountain Lake, Greenville, Virginia.

1.2.6 Purpose of Dam: The dam is used for flood control and recreation.

1.2.7 Design and Construction History: The existing facility was designed by the SCS. The dam, completed in 1959, was constructed by the George Via Construction Company.

1.2.8 Normal Operational Procedures: The reservoir is normally operated at the level of the fixed crest riser, elevation 1601.5 feet M.S.L. No formal operating procedures are followed for this structure. See paragraph 4.1 for detailed operating procedures.

1.3 Pertinent Data

1.3.1 Drainage Area: The drainage area for South River No. 6 dam is 4.1 square miles.

1.3.2 Discharge at Dam Site: Maximum discharge at the dam site is unknown. The owner indicated that water has never reached the emergency spillway level since dam construction.

Principal Spillway:

Pool level at top of dam 86 c.f.s.

Emergency Spillway:

Pool level at top of dam 10,786 c.f.s.

1.3.3 Dam and Reservoir Data: Pertinent data on the dam and reservoir are shown in the following table:

NAME OF DAM: SOUTH RIVER No. 6

TABLE 1.1 DAM AND RESERVOIR DATA

Item	Elevation feet M.S.L.	Area acres	Reservoir Capacity		Length feet
			Acre- feet(a)	Watershed inches	
Top of dam	1642.0	52.0	1263	5.8	2200
Emergency spillway invert	1635.0	49.2	885	4.1	2060
Principal spillway crest (normal pool)	1601.5	12.3	30.2	0.1	935
Streambed at downstream toe of dam	1586.1	-	-	-	-

(a) Includes sediment storage of 30.2 acre-feet.

NAME OF DAM: SOUTH RIVER No. 6

SECTION 2 - ENGINEERING DATA

- 2.1 Design: The geologic and design reports and the as-built plans were available for use in preparing this report. (Other information, such as soils laboratory testing and slope stability analyses, was not available.) The geology report was prepared by L.A. Gorman, Geologist from the Richmond, Virginia office of the SCS. Glenn W. Grubb, Design and Construction Engineer, from the Upper Darby, Pennsylvania office of the SCS, prepared the design report.

The original geologic investigation was conducted during August of 1957. Soil samples were taken from twelve feet deep and later analyzed. After the results were reviewed, further and deeper investigations were deemed necessary to collect additional samples for triaxial shear and time compaction² tests. The results of the lab tests were not available for use in the preparation of this report. According to the geology report, the dam site is covered by alluvial material and no bedrock outcrops in the vicinity of the structure. The bedrock under the alluvium includes shale, sandstone, limestone, and dolomite which can weather into the type of residual clay soil found in the area.

Along the centerline of the dam (within the valley floor and through the east and west abutment), 10 test pits were dug and 4 test borings were cored. The soil and rock profile indicated that the foundation appeared adequate to support the dam structure and that the abutments appeared sound. The east abutment material was more dense and harder than that of the west abutment and valley floor. Tests also indicated that some leakage might occur along the valley floor, but that it would be controlled by the drains. (Conditions under the proposed principal spillway were similar to those of the valley floor, and it was suggested that the spillway be located in the east abutment. It was subsequently located on the floodplain.)

The geologic report indicated that adequate borrow material would be available; however, the report strongly suggested that no material be removed from the permanent pool area. (Pertinent sections of the Geologic Report may be found in Appendix V.)

²Apparently consolidation.

After review of the geologic data, the design report called for the construction of a compacted earth dam atop alluvium and alluvial terrace material. The proposed principal spillway would be a drop inlet type with a reinforced 24 inch inside diameter concrete pipe and a reinforced concrete riser resting on silty clay. The emergency spillway was excavated into silty sand and clay of the left abutment. Hydrologic/hydraulic design data from this report is discussed in paragraph 5.1.

2.2 Construction: As-built drawings were available for review and were subsequently verified in the field. Construction was performed by the George Via Construction Company and was completed in 1959.

2.3 Evaluation:

2.3.1 Design: The as-built drawings and design report were available to assess most aspects of design. The hydrologic and hydraulic data provided were adequate for design review. The assessments made in this report are based on the design data along with field observations and office analyses.

2.3.2 Construction: No construction logs were available for review. The width of the emergency spillway was changed from 150 to 175 feet some time after the original design work was performed and the surface area of the normal pool was reduced from 37 acres to 12.3 acres. Other than these changes, the as-built drawings do not indicate any changes or modifications that were made during construction.

NAME OF DAM: SOUTH RIVER No. 6

SECTION 3 - VISUAL INSPECTION

3.1 Findings

- 3.1.1 General: The field inspection was conducted on 14 November 1979. Skies were overcast and the temperature was 38°F. At the time of the inspection, the pool elevation was 1601.8 feet M.S.L. and the tailwater elevation was 1586.1 feet M.S.L. Ground conditions were somewhat damp due to previous rain showers. The embankment and appurtenant structures were found to be in good condition. The following are brief summaries of deficiencies found during the inspection. A Field Sketch of conditions is shown on Plate 1. The complete visual inspection check list is given in Appendix III. The Headwaters Soil and Water Conservation District conducts a yearly inspection program for the dam with the assistance of the District Conservationist, and deficiencies which are found are corrected in conjunction with this inspection. The report on the 1978 inspection is given in Appendix IV.
- 3.1.2 Dam: The embankment was found to be in good condition with no surface cracks, slumps or sloughs, or other indications of instability either on the embankment or at the toe. The slopes are generally well covered with grass; however, there are areas of sparse, dried out vegetation stretching horizontally across the embankment below the bench. These areas should be reseeded. Wave erosion is taking place on the upstream face. There is an animal burrow on the right side of the downstream embankment near the toe.
- 3.1.3 Appurtenant Structures: The principal spillway intake is a rectangular concrete riser with a drop inlet. The concrete on the riser is in good condition with no visible signs of cracking or spalling. There is no trash rack on the riser, but there was no noticeable debris around the intake. The outlet structure is a 24 inch steel-lined concrete pipe protruding from a concrete head wall. The structure is in good condition. One toe drain outlet is present and located to the left of the principal spillway outlet. The toe drain was

NAME OF DAM: SOUTH RIVER No. 6

not flowing at the time of the inspection. The emergency spillway is well defined and well vegetated with grass. The emergency spillway has a bottom width of 175 feet, as measured during the inspection. The campground's access road and office/store building are located within the spillway. The construction of the building by the previous owner was not authorized by the SCS or the conservation district. The SCS and the conservation district have instructed the present owner that addition to or occupation of the building is strictly prohibited. No other major obstructions are present.

3.1.4 Reservoir Area: The reservoir functions as a swimming and fishing area for the campground. The principal spillway intake is covered by a platform/dock structure complete with diving board. Additional docks are present along the shore. Sand cover along the right shoreline creates an artificial beach for campers. There are grassy and wooded gradual slopes on the left and upstream shoreline. The right side is wooded and more steeply sloped. Three streams (Cold Spring Branch, Deep Pond Run, Gum Springs Branch) empty into the reservoir. The design report estimated a sedimentation rate of 0.604 acre-feet per year for the reservoir area.

3.1.5 Downstream Channels: The channel is fairly clear; however, the overbank areas are wooded. There are three houses and two mobile homes located downstream.

3.2 Evaluation: In general, the dam and appurtenant structures are in good condition. Seeding is recommended for the brown and dormant vegetation areas. The animal burrow should be filled. The berm on the upstream face should be observed during annual inspections and riprap should be installed if erosion continues.

The owner should give serious consideration to relocating the campground office/store from the emergency spillway to an elevation higher than the dam crest.

SECTION 4 - OPERATIONAL PROCEDURES

4.1 Procedures: The reservoir is used for recreation and flood control and as such operation is automatic. The normal pool is maintained at elevation 1601.5 feet M.S.L. by means of the fixed crest of the principal spillway riser. When inflow to the reservoir exceeds the principal spillway capacity, water will rise behind the dam, creating a larger pool. During a major storm, inflows may be sufficient to discharge waters over the emergency spillway around the dam and back into the downstream channel.

4.2 Maintenance of Dam: The Headwaters Soil and Water Conservation District is responsible for the maintenance of the dam. The annual maintenance responsibilities include liming, fertilizing, and mowing the embankment and spillways; seeding and mulching bare areas; and repairing gullies that occur in the dam and spillway areas.

4.3 Maintenance of Operating Facilities: The Headwaters Soil and Water Conservation District is responsible for the maintenance of the emergency drawdown facilities. Additionally, the owner assists the District in the normal maintenance of the structure as part of his operation of the campgrounds.

The emergency drawdown head gate on the principal spillway riser is operable, according to the owner. However, the previous owner reportedly had difficulty resealing the gate.

4.4 Warning System: At the present time, there is no formal warning system or evacuation plan in operation.

4.5 Evaluation: Maintenance of the dam is considered adequate. A warning system should be installed to warn campers and downstream residents of rising waters in the reservoir. This system should be based upon the rate of rise of the flood pool and its relation to adequate notification time to campers and downstream residents. An emergency action plan should also be implemented. The emergency action plan should contain instructions that the campground office/store is not to be used by campers for shelter during periods of heavy rain. Both the warning system and the emergency action plan should be approved by the state and the conservation district. The owner should contact the SCS about possible replacement or repair of the emergency drawdown head gate.

NAME OF DAM: SOUTH RIVER No. 6

SECTION 5 - HYDRAULIC/HYDROLOGIC DATA

- 5.1 Design: Normal pool (elevation 1601.5 feet M.S.L.) is maintained by fixed crest drop inlet structure with a total weir length of 12.0 feet and a 24 inch reinforced concrete outlet pipe. The weir crest was established at the elevation sufficient to store the 50-year sediment accumulation.

The crest (elevation 1635.0 feet M.S.L.) of the emergency spillway was established at the elevation needed to store the 100-year flood. The elevation of the top of dam (1642.0 feet M.S.L.) was established by use of the freeboard hydrograph. The freeboard hydrograph was developed for a class "C" structure and was obtained by using a 6-hour point rainfall of 27.3 inches.

- 5.2 Hydrologic Records: No rainfall or stream flow records were available at the dam site.
- 5.3 Flood Experience: No exact high water marks were available. The owner indicated that the water level has never approached the crest of the emergency spillway.
- 5.4 Flood Potential: The Probable Maximum Flood (PMF) and the 1/2 Probable Maximum Flood (1/2 PMF) were developed and routed through the reservoir by use of the HEC-1 DB computer program (Reference 9, Appendix VIII) and appropriate unit hydrograph, precipitation, and storage-discharge data. Clark's T_c and R coefficients for the local drainage areas were estimated from basin characteristics. The rainfall applied to the unit hydrograph was obtained from the National Oceanic and Atmospheric Administration's publication (Reference 17, Appendix VIII). Losses were estimated at an initial loss of 1.0 inch and a constant loss thereafter of 0.05 inch per hour.
- 5.5 Reservoir Regulation: Pertinent dam and reservoir information are shown in Table 1.1, paragraph 1.3.3.

Regulation of flow from the reservoir is automatic. Normal flows are maintained by the weir crest of the principal spillway inlet structure with an elevation of 1601.5 feet M.S.L. Water entering over the crest of this inlet structure flows through the dam in a 24 inch diameter reinforced concrete conduit. Water also flows past the dam through the ungated, vegetated, emergency spillway in the event water in the reservoir rises above an elevation of 1635.0 feet M.S.L.

NAME OF DAM: SOUTH RIVER No. 6

Discharge capacity for the principal and emergency spillways was computed by hand; reservoir area and storage capacity were taken from the SCS design report and extrapolated for elevations above the top of dam. The flood routings were begun with the reservoir level at normal pool.

- 5.6 Overtopping Potential: The probable rise of the reservoir and other pertinent information on reservoir performance are shown in the following table:

TABLE 5.1 RESERVOIR PERFORMANCE

Item	Normal(a)	Hydrographs	
		1/2 PMF	PMF(b)
Peak flow, c.f.s.			
Inflow	5	8,935	17,871
Outflow	5	8,620	17,798
Peak elev., ft. M.S.L.	1601.8	1641.05	1643.32
Emergency spillway (c) (elev. 1635.0 feet M.S.L.)			
Depth of flow, ft.	-	6.0	8.3
Average velocity, f.p.s.	-	11.4	13.4
Duration of flow, hrs.	-	9.5	13.8
Non-overflow section (c) (elev. 1642.0 feet M.S.L.)			
Depth of flow, ft.	-	-	1.3
Average velocity, f.p.s.	-	-	5.3
Total duration of overtopping hrs.	-	-	3.0
Tailwater elev., ft. M.S.L.	1586.1	-	-

- (a) Conditions at time of inspection.
 (b) The PMF is an estimate of flood discharges that may be expected from the most severe combination of critical meteorologic and hydrologic conditions that are reasonably possible in the region.
 (c) Depth and velocity estimates were based on critical depth at control section.

- 5.7 Reservoir Emptying Potential: A 24 inch circular head gate located on the principal spillway riser is available to dewater the reservoir. The gate is operated from the top of the riser platform. Neglecting inflow, the reservoir can be drawn down from normal pool in approximately 1 day. This is equivalent to an approximate drawdown rate of 8.5 feet per day based on the hydraulic height measured from normal pool divided by the time to dewater the reservoir.

NAME OF DAM: SOUTH RIVER No. 6

5.8 Evaluation: South River No. 6 dam is an "intermediate" size - "high" hazard dam requiring evaluation for a spillway design flood (SDF) equal to the PMF. The PMF was routed through the reservoir and found to overtop the dam by a maximum depth of approximately 1.3 feet with an average critical velocity of 5.3 f.p.s. Total duration of overtopping would be approximately 3.0 hours. The spillway is capable of passing only 60 percent of the PMF.

Conclusions pertain to present day conditions and the effect of future development on the hydrology has not been considered.

NAME OF DAM: SOUTH RIVER No. 6

SECTION 6 - DAM STABILITY

6.1 Foundation and Abutments: A geology report prepared by the SCS was available for use in preparing this report. Excerpts from the geology report are given in Appendix V. South River No. 6 dam is located in the Shenandoah Valley region of Virginia. No bedrock outcrops in the vicinity of the dam site because the area is covered by alluvial material. The rocks which are present under the alluvium include the Waynesboro formation, Elbrook Dolomite, and Conococheague Limestone. These formations include shale, sandstone, limestone, and dolomite, which can weather into the type of clay deposits found in this vicinity. According to the as-built plans furnished by the SCS, the seepage drain consists of a 3 foot by 4 foot filter of pit-run sand and gravel running the length of the embankment. The central section of this bed contains a perforated, 6 inch diameter bituminous coated corrugated metal pipe. Near the principal spillway conduit, this pipe connects with a non-perforated, 6 inch corrugated metal pipe which discharges into the stilling basin. According to the as-built plans, the dam is keyed into the foundation.

6.2 Embankment

6.2.1 Materials: It is known that the embankment materials came from the vicinity of the dam. The alluvial terrace material in this area consists of weathered sandstone cobbles and gravel, and low-plastic, sandy silts and clays; as stated in to the SCS geology report. The as-built plans show that the embankment is zoned.

6.2.2 Stability: There are no available stability calculations. the dam is 56 feet high and 17 feet wide. it has a measured upstream slope of 3H:1V and a measured downstream slope of 2.5H:1V. The dam exists at normal storage pool. The reservoir level has never yet approached the elevation of the emergency spillway. The dam has a freeboard of approximately 33.5 feet from maximum control storage. The dam is subjected to a sudden drawdown because the approximate reservoir drawdown rate of 8.5 feet per day exceeds the critical rate of 0.5 foot per day for earth dams. According to the guidelines presented in Design of Small Dams, U.S. Department of the Interior, Bureau of Reclamation, for small

NAME OF DAM: SOUTH RIVER No. 6

homogeneous dams with a stable foundation, subjected to a drawdown, and composed of low-plastic fines (CL, ML); the recommended slopes are 3H:1V upstream and 2.5H:1V downstream. The recommended width is 21 feet. Based on these guidelines and considering the fact that there is a 10 feet wide bench on the downstream embankment, the width and embankment slopes are considered to be adequate.

6.2.3 Seismic Stability: The dam is located in Seismic Zone 2. Therefore, according to the Recommended Guidelines for Safety Inspection of Dams, the dam is considered to have no hazard from earthquakes provided static stability conditions are satisfactory and conventional safety margins exist.

6.3 Evaluation: There is insufficient information to adequately evaluate the stability of the dam. However, the visual inspection revealed no apparent instability. Also, based on the Bureau of reclamation guidelines, the dam's width and slopes are adequate. Based on these conditions, the embankment is considered stable for normal pool conditions. Maximum control storage conditions are unknown.

Despite the inability of the spillway to pass the design flood, the depth, duration, and rate of overtopping flows are not considered detrimental to the embankment. Overtopping flows are shallow, last only 3 hours, and the velocity is less than 6 f.p.s., the effective eroding velocity for a vegetated earth embankment.

Based on the above, stability calculations are not required.

NAME OF DAM: SOUTH RIVER No. 6

SECTION 7 - ASSESSMENT/REMEDIAL MEASURES

- 7.1 Dam Assessment: The dam and appurtenant structures are generally in good overall condition. No deficiencies were discovered during the field inspection and office analysis which would indicate the need for emergency attention.

Using the Corps of Engineers' screening criteria for initial review of spillway adequacy, the PMF was selected as the SDF for the "intermediate" size - "high" hazard classification of South River No. 6 dam. It has been determined that the dam would be overtopped by the SDF to a maximum depth of 1.3 feet with an average critical velocity of 5.3 f.p.s. and would remain above the top of dam for 3.0 hours. The spillway is capable of passing only 60 percent of the PMF and is therefore adjudged as inadequate, but not seriously inadequate.

Since access to the campground above the dam is through the emergency spillway and may be cut off during a major flood, a warning system should be developed and put into operation. An emergency action plan should also be implemented.

The other recommended remedial measures are not considered urgent and therefore may be accomplished as part of an annual maintenance and inspection program.

- 7.2 Recommended Remedial Measures: A warning system should be installed to warn campers and downstream residents of rising waters in the reservoir. This system should be based upon the rate of rise of the flood pool and its relation to adequate notification time to campers and downstream residents. An emergency action plan should also be implemented. Both the warning system and the emergency action plan should be approved by the state and the conservation district.

It is recommended that the following repair items be accomplished as part of an annual maintenance program: fill animal burrows and small erosion channels, reseed the areas of sparse vegetation on the embankment, and install a staff gage in the reservoir. The owner should contact the local Soil and Water Conservation District about possible replacement or repair of the emergency drawdown valve, which is reportedly operable but difficult to reseal.

The owner should also give serious consideration to relocating the campground office/store from the emergency spillway to an elevation higher than the dam crest.

NAME OF DAM: SOUTH RIVER No. 6

APPENDIX I

PLATES

CONTENTS

Location Plan

Plate 1: Field Sketch

Plate 2: Plan of Dam

Plate 3: Section Along Centerline of Principal Spillway


Plate 4: Details of Seepage Drain

Plate 5: Profiles and Soils Information


Note: On Plate 5, the emergency spillway width is shown as 150 feet. On Plate 2, the emergency spillway width is shown as 175 feet. During the inspection, the width of the emergency spillway was measured as 175 feet.

NAME OF DAM: SOUTH RIVER No. 6

**SOUTH RIVER
NO. 6 DAM**



VA.




SOUTH RIVER NO.6 DAM
LOCATION PLAN

FIELD SKETCH


SOUTH RIVER DAM #6
MICHAEL BAKER, JR., INC.
14 NOVEMBER 1979


PLATE I



NOTE:
BENCH ON DOWNSTREAM EMBANKMENT TILTS BACK TOWARD THE EMBANKMENT —
STANDING WATER PRESENT IN TROUGH ON BENCH
MANY MOLE BURROWS / TRACKS PRESENT ON DAM

NO SCALE






As Built

PLATE 2

DAM NO. 3 GOLD SPRINGS	
SOUTH RIVER SUB-APPROPRIATION	
POTOMAC RIVER WATERSHED DISTRICT, VIRGINIA	
SITE LOCATION MAP	
U.S. DEPARTMENT OF AGRICULTURE	
SOIL CONSERVATION SERVICE	
Scale	1 inch = 1 mile
North Arrow	
Legend	
Contour Lines	100, 200, 300, 400, 500, 600, 700, 800, 900, 1000
Roads	1/2 inch wide, 1/4 inch wide, 1/8 inch wide
Water	Blue line, Blue area
Settlements	Black dots, Black area
Other	

Contour Lines
 100 200 300 400 500 600 700 800 900 1000
 Roads
 1/2 inch wide 1/4 inch wide 1/8 inch wide
 Water
 Blue line Blue area
 Settlements
 Black dots Black area
 Other

Scale 1" = 1 mile
 North Arrow



PROFILE OF PRINCIPAL SPILLWAY
SCALE: HORIZ. 1"=20'; VERT. 1"=10.0'

POINT	DISTANCE FROM DISCHARGE END OF INVERT OF 24" PIPE (FT)	ELEVATION OF INVERT OF 24" PIPE
A	0	1536.1
B	16	1586.46
C	32	1586.82
D	48	1587.18
E	64	1587.54
F	80	1587.90
G	96	1588.26
H	112	1588.62
I	128	1588.98
J	144	1589.34
K	160	1589.70
L	176	1590.06
M	192	1590.42
N	208	1590.78
O	224	1591.14
P	240	1591.50
Q	256	1591.86
R	272	1592.22
S	288	1592.58
T	304	1592.94
U	320	1593.30
V	336	1593.66
W	352	1594.02
X	368	1594.38
Y	384	1594.74
Z	400	1595.10
AA	416	1595.46
AB	432	1595.82
AC	448	1596.18
AD	464	1596.54
AE	480	1596.90
AF	496	1597.26
AG	512	1597.62
AH	528	1597.98
AI	544	1598.34
AJ	560	1598.70
AK	576	1599.06
AL	592	1599.42
AM	608	1599.78
AN	624	1600.14
AO	640	1600.50
AP	656	1600.86
AQ	672	1601.22
AR	688	1601.58
AS	704	1601.94
AT	720	1602.30
AU	736	1602.66
AV	752	1603.02
AW	768	1603.38
AX	784	1603.74
AY	800	1604.10
AZ	816	1604.46
BA	832	1604.82
BB	848	1605.18
BC	864	1605.54
BD	880	1605.90
BE	896	1606.26
BF	912	1606.62
BG	928	1606.98
BH	944	1607.34
BI	960	1607.70
BJ	976	1608.06
BK	992	1608.42
BL	1008	1608.78
BM	1024	1609.14
BN	1040	1609.50
BO	1056	1609.86
BP	1072	1610.22
BQ	1088	1610.58
BR	1104	1610.94
BS	1120	1611.30
BT	1136	1611.66
BU	1152	1612.02
BV	1168	1612.38
BW	1184	1612.74
BX	1200	1613.10
BY	1216	1613.46
BZ	1232	1613.82
CA	1248	1614.18
CB	1264	1614.54
CC	1280	1614.90
CD	1296	1615.26
CE	1312	1615.62
CF	1328	1615.98
CG	1344	1616.34
CH	1360	1616.70
CI	1376	1617.06
CJ	1392	1617.42
CK	1408	1617.78
CL	1424	1618.14
CM	1440	1618.50
CN	1456	1618.86
CO	1472	1619.22
CP	1488	1619.58
CQ	1504	1619.94
CR	1520	1620.30
CS	1536	1620.66
CT	1552	1621.02
CU	1568	1621.38
CV	1584	1621.74
CW	1600	1622.10
CX	1616	1622.46
CY	1632	1622.82
CZ	1648	1623.18
DA	1664	1623.54
DB	1680	1623.90
DC	1696	1624.26
DD	1712	1624.62
DE	1728	1624.98
DF	1744	1625.34
DG	1760	1625.70
DH	1776	1626.06
DI	1792	1626.42
DJ	1808	1626.78
DK	1824	1627.14
DL	1840	1627.50
DM	1856	1627.86
DN	1872	1628.22
DO	1888	1628.58
DP	1904	1628.94
DQ	1920	1629.30
DR	1936	1629.66
DS	1952	1630.02
DT	1968	1630.38
DU	1984	1630.74
DV	2000	1631.10
DW	2016	1631.46
DX	2032	1631.82
DY	2048	1632.18
DZ	2064	1632.54
EA	2080	1632.90
EB	2096	1633.26
EC	2112	1633.62
ED	2128	1633.98
EE	2144	1634.34
EF	2160	1634.70
EG	2176	1635.06
EH	2192	1635.42
EI	2208	1635.78
EJ	2224	1636.14
EK	2240	1636.50
EL	2256	1636.86
EM	2272	1637.22
EN	2288	1637.58
EO	2304	1637.94
EP	2320	1638.30
EQ	2336	1638.66
ER	2352	1639.02
ES	2368	1639.38
ET	2384	1639.74
EU	2400	1640.10
EV	2416	1640.46
EW	2432	1640.82
EX	2448	1641.18
EY	2464	1641.54
EZ	2480	1641.90
FA	2496	1642.26
FB	2512	1642.62
FC	2528	1642.98
FD	2544	1643.34
FE	2560	1643.70
FF	2576	1644.06
FG	2592	1644.42
FH	2608	1644.78
FI	2624	1645.14
FJ	2640	1645.50
FK	2656	1645.86
FL	2672	1646.22
FM	2688	1646.58
FN	2704	1646.94
FO	2720	1647.30
FP	2736	1647.66
FQ	2752	1648.02
FR	2768	1648.38
FS	2784	1648.74
FT	2800	1649.10
FU	2816	1649.46
FV	2832	1649.82
FW	2848	1650.18
FX	2864	1650.54
FY	2880	1650.90
FZ	2896	1651.26
GA	2912	1651.62
GB	2928	1651.98
GC	2944	1652.34
GD	2960	1652.70
GE	2976	1653.06
GF	2992	1653.42
GG	3008	1653.78
GH	3024	1654.14
GI	3040	1654.50
GO	3056	1654.86
GP	3072	1655.22
GQ	3088	1655.58
GR	3104	1655.94
GS	3120	1656.30
GT	3136	1656.66
GU	3152	1657.02
GV	3168	1657.38
GW	3184	1657.74
GX	3200	1658.10
GY	3216	1658.46
GZ	3232	1658.82
HA	3248	1659.18
HB	3264	1659.54
HC	3280	1659.90
HD	3296	1660.26
HE	3312	1660.62
HF	3328	1660.98
HG	3344	1661.34
HH	3360	1661.70
HI	3376	1662.06
HJ	3392	1662.42
HK	3408	1662.78
HL	3424	1663.14
HM	3440	1663.50
HN	3456	1663.86
HO	3472	1664.22
HP	3488	1664.58
HQ	3504	1664.94
HR	3520	1665.30
HS	3536	1665.66
HT	3552	1666.02
HU	3568	1666.38
HV	3584	1666.74
HW	3600	1667.10
HX	3616	1667.46
HY	3632	1667.82
HZ	3648	1668.18
IA	3664	1668.54
IB	3680	1668.90
IC	3696	1669.26
ID	3712	1669.62
IE	3728	1669.98
IF	3744	1670.34
IG	3760	1670.70
IH	3776	1671.06
II	3792	1671.42
IJ	3808	1671.78
IK	3824	1672.14
IL	3840	1672.50
IM	3856	1672.86
IN	3872	1673.22
IO	3888	1673.58
IP	3904	1673.94
IQ	3920	1674.30
IR	3936	1674.66
IS	3952	1675.02
IT	3968	1675.38
IU	3984	1675.74
IV	4000	1676.10
IV	4000	1676.10




PLATE 3


As Built

DAM NO. 6 COLD SPRINGS
SOUTH RIVER SUB-WATERSHED
POTOMAC RIVER WATERSHED, AUGUSTA CO., VIRGINIA
SECTION ALONG E OF PRINCIPAL SPILLWAY


U. S. DEPARTMENT OF AGRICULTURE
SOIL CONSERVATION SERVICE

Project	NO. 6 COLD SPRINGS	Sheet	3 of 3
Drawn by	R. J. MORGAN	Checked by	R. J. MORGAN
Date	11/10/50	Scale	1"=10.0'
Location	VA-336-P	Project	NO. 6 COLD SPRINGS


DETERMINED BY ENGINEER AFTER
TOPSOIL IS REMOVED





PLAN VIEW OF SEEPAGE DRAIN



DESIGNED BY ENGINEER ARTHUR
 BRUSH 15 REMOVED




SECTION ALONG L OF SEEPAGE DRAIN
 NOT TO SCALE



NOTE:
 WHERE ONLY FILTER MATERIAL IS USED THIS
 SECTION IS THE SAME EXCEPT THAT THE
 PIPE IS OMITTED.

PIT-RUN SAND & GRAVEL
 OR 1:2 MIXTURE OF CON-
 CRETE SAND & COARSE
 AGGREGATE AS SPECIFIED

6" DIA. BIE COATED C.M.P.
 DIA. OF PERFORATIONS 3/8"
 PERFORATIONS DOWN




TYPICAL SECTION OF SEEPAGE DRAIN
 SCALE: 1" = 2'-0"


As Built

PLATE 4

DAM NO. 6 COLD SPRINGS	
SOUTH RIVER SUB-WATERSHED	
POTOMAC RIVER WATERSHED, AUGUSTA CO., VIRGINIA	
DETAILS OF SEEPAGE DRAIN	
U.S. DEPARTMENT OF AGRICULTURE	
SOIL CONSERVATION SERVICE	
Designed by E. F. HUBBARD 5-18-50	Checked by H. W. WILSON 5-2-50
Drawn by T. H. MORGAN 5-20-50	Field notes 100
Scale 1" = 2'-0"	Sheet No. VA-336-



FOR LOCATION OF SOIL BORINGS AND PITS
 SEE PLAN VIEW SHEET 3 OF 10







PLATE 5

DAM NO. 6 COLD SPRINGS
SOUTH RIVER SUB-WATERSHED
POTOMAC RIVER WATERSHED, AUGUSTA CO., VIRGINIA
PROFILES & SOILS INFORMATION

U.S. DEPARTMENT OF AGRICULTURE
SOIL CONSERVATION SERVICE

Designed by N.W. WILSON	5-1-58	Reviewed by H.T. BROWNING	5-21-58
Drawn by H.T. BROWNING	5-21-58	Checked by B. J. WENGER	June 58

Project No. **VA-336-P**

APPENDIX II

PHOTOGRAPHS

CONTENTS

- Photo 1: Principal Spillway Riser with Lift Pedestal for Reservoir Drain
- Photo 2: Outlet Conduit and Stilling Pool, Toe Drain Outlet Located to the Right
- Photo 3: Emergency Spillway Approach Channel (Background) and Small Erosion Berm Forming at Waters Edge
- Photo 4: Location of Office/Store in the Emergency Spillway Approach Channel
- Photo 5: Exit Channel of Emergency Spillway (Background) Note Well Maintained Condition of Embankment
- Photo 6: Downstream Damage Area

Note: Photographs were taken on 14 November 1979.

NAME OF DAM: SOUTH RIVER No. 6

SOUTH RIVER No. 6 DAM




PHOTO 1. Principal Spillway Riser with Lift Pedestal for Reservoir Drain



**PHOTO 2. Outlet Conduit and Stilling Pool, Toe Drain Outlet
Located to the Right**

SOUTH RIVER No. 6 DAM



**PHOTO 3. Emergency Spillway Approach Channel (Background) and
Small Erosion Berm Forming at Waters Edge**



**PHOTO 4. Location of Office/Store in the Emergency Spillway
Approach Channel**

SOUTH RIVER No. 6 DAM



**PHOTO 5. Exit Channel of Emergency Spillway (Background)
Note Well Maintained Condition of Embankment**



PHOTO 6. Downstream Damage Area

APPENDIX III

VISUAL INSPECTION CHECK LIST

Check List
Visual Inspection
Phase 1

Name of Dam South River No. 6 County Augusta State Virginia Coordinates Lat. N3759.5°
Long. W7907.4°

Date of Inspection 14 November 1979 Weather Overcast Temperature 38°F.

Pool Elevation at Time of Inspection 1601.8 ft. M.S.L. Tailwater at Time of Inspection 1586.1 ft. M.S.L.

11111

Inspection Personnel:
Michael Baker, Jr., Inc.:

David J. Greenwood, P.E.
Jeffrey A. Quay
Leslie K. Black

Virginia Water Control Board:

Leon Musselwhite
David Bushman

Owner's Representatives:

David Willingham (owner)

David J. Greenwood Recorder

EMBANKMENT

Name of Dam: SOUTH RIVER No. 6

VISUAL EXAMINATION OF	OBSERVATIONS	REMARKS OR RECOMMENDATIONS
SURFACE CRACKS	None visible	
UNUSUAL MOVEMENT OR CRACKING AT OR BEYOND THE TOE	None	
SLOUGHING OR EROSION OF EMBANKMENT AND ABUTMENT SLOPES	There is minor erosion on the right downstream embankment where it joins the abutment. The slopes are generally well covered with grass; however, there are areas of sparse, dried out vegetation stretching horizontally across the embankment below the bench.	The areas where erosion has begun should be filled and reseeded. Areas of sparse vegetation on the downstream embankment should also be reseeded.
VERTICAL AND HORIZONTAL ALIGNMENT OF THE CREST	The horizontal and vertical alignments of the crest are good. There is an animal burrow on the right side of the downstream embankment near the toe.	The animal burrow should be filled and reseeded.
RIPRAP FAILURES	There is no riprap on the dam face. An erosion berm is just beginning to form at the water's edge.	The erosion should be checked periodically. Consideration should be given to placing riprap at the normal pool elevation.

EMBANKMENT

Name of Dam: SOUTH RIVER No. 6

VISUAL EXAMINATION OF	OBSERVATIONS	REMARKS OR RECOMMENDATIONS
JUNCTION OF EMBANKMENT AND ABUTMENT, SPILLWAY AND DAM	The junctions are well seeded and show little sign of erosion except for some small areas along the right downstream abutment.	The areas where erosion has begun should be filled and reseeded.
ANY NOTICEABLE SEEPAGE	None visible	The normal pool is quite low and provides very little hydraulic head above the toe.
STAFF GAGE AND RECORDER	None	A staff gage should be installed.
DRAINS	A toe drain is shown on the as-built drawings. The outlet pipe for the toe drain is located on the left side of the primary spillway outlet. The toe drain was not flowing at the time of the inspection.	The silty clay materials used in the dam should allow continual seepage through the toe. If no flow is ever observed, the drain has probably been plugged and should be reamed.

OUTLET WORKS

Name of Dam: SOUTH RIVER No. 6

VISUAL EXAMINATION OF	OBSERVATIONS	REMARKS OR RECOMMENDATIONS
CRACKING AND SPALLING OF CONCRETE SURFACES IN OUTLET CONDUIT	The conduit is a 24 in. steel pipe encased in concrete. The concrete and steel appear to be in good condition.	
INTAKE STRUCTURE	The intake structure is an old SCS type box riser with four-directional inflow controlled by a fixed concrete crest. The concrete on the riser is in good condition, with no visible signs of cracking or spalling. There was no debris around the intake at the time of the inspection.	
OUTLET STRUCTURE	The outlet structure is a 24 in. concrete pipe over a steel liner, protruding from a concrete head wall. The concrete on both the pipe and the head wall was in good condition at the time of the inspection.	
OUTLET CHANNEL	The outlet channel is in good condition and shows no signs of erosion even after recent heavy storms. The riprapped stilling basin was submerged during the inspection.	
EMERGENCY GATE	The emergency gate, located on the intake structure, is operable, according to the owner. The previous owner reportedly had considerable trouble resealing the gate.	According to the owner, owners of other SCS dams of approximately the same age as this one are also experiencing problems with their emergency gates. The SCS is investigating.

UNGATED SPILLWAY

Name of Dam: SOUTH RIVER No. 6

VISUAL EXAMINATION OF	OBSERVATIONS	REMARKS OR RECOMMENDATIONS
CONCRETE WEIR	None	
APPROACH CHANNEL	<p>The campground office and store is located in the approach channel. The entrance road to the campground is located in the spillway. Other than the office and store, there are no major obstructions in the approach channel. The channel is well vegetated with grass and is mowed regularly.</p>	<p>The SCS and the conservation district have both advised the owner that he may not make any additions to the building in the spillway, and warned him that he will lose the building if a major flood occurs. The building should be removed because it restricts flow through the spillway. The building was constructed by the previous owner of the dam.</p>
DISCHARGE CHANNEL	<p>There are no major obstructions in the discharge channel. The discharge channel is well vegetated with grass and is mowed regularly.</p>	
BRIDGE AND PIERS	None	

INSTRUMENTATION

Name of Dam: SOUTH RIVER No. 6

<u>VISUAL EXAMINATION</u>	<u>OBSERVATIONS</u>	<u>REMARKS OR RECOMMENDATIONS</u>
MONUMENTATION/SURVEYS	Permanent markers were not found.	
OBSERVATION WELLS	None observed	
WEIRS	None observed	
PIEZOMETERS	None observed	
OTHER		

RESERVOIR

Name of Dam: SOUTH RIVER No. 6

VISUAL EXAMINATION OF		OBSERVATIONS	REMARKS OR RECOMMENDATIONS
SLOPES	The slopes on the left side and the upstream end of the reservoir are gradual. The hillside on the steeper right side of the reservoir shows no signs of slumping or erosion. Sand has been placed on the right side to create a beach. The slopes on the left side of the reservoir are grassy and wooded; those on the right side are wooded.		
SEDIMENTATION	None was observed during the inspection. In the SCS design report, sedimentation was estimated as 0.604 ac.-ft. per year.		
TRIBUTARIES	The reservoir is fed by three streams: Cold Spring Branch, Deep Pond Run, and Gum Springs Branch.		

DOWNSTREAM CHANNEL

Name of Dam: SOUTH RIVER No. 6

VISUAL EXAMINATION OF	OBSERVATIONS	REMARKS OR RECOMMENDATIONS
-----------------------	--------------	----------------------------

CONDITION (OBSTRUCTIONS, DEBRIS, ETC.)	The channel is fairly clear; the channel banks appear to be stable.	
--	---	--

SLOPES	The downstream channel is fairly steep, with a slope of approximately 2.7%. Vegetation in the overbanks consists of moderately dense trees and brush.	
--------	---	--

APPROXIMATE NO. OF HOMES AND POPULATION	The downstream damage area contains three houses and two mobile homes; the number of occupants is estimated at twenty.	The campground office and store in the emergency spillway is also in the damage reach.
---	--	--

APPENDIX IV

OPERATION AND MAINTENANCE INSPECTION REPORT

OPERATION AND MAINTENANCE INSPECTION

of

South River Watershed Structures

An inspection team of Jackson Betts, Wayne Hypes, John Crist, Folger Taylor, and William E. Lucas, Jr. on April 5, 1978, visited the following dams of the South River Watershed of the Potomac River Watershed.

Site #3 - Greenville Correction Center - The dam is in good shape with good vegetative cover and has been mowed. Posts have been set to indicate firing stations in the emergency spillway and using the spillway bank as a pellet stop. When the firing training is completed the posts should be removed. This structure is being used rather wisely.

Site #4 - Kiwanis Lake - The spillway pipe and riser appear to be in good shape. All of the dam has been mowed. The Ky 31 is becoming thin on the front of the dam (wet side) and needs to be overseeded with Ky 31 and fertilized. The road on the top of the dam needs to be graveled on the steeper parts. The back part of the dam (dry side) has some woody growth that should be cut and deadened. There is about 1 Ac. that needs to be seeded to Ky 31. The entire dam and emergency spillway area should be limed and fertilized.

Site #6 - Sangers Lake - This structure is kept mowed. Some overseeding of Ky 31 would be helpful. Some Crownvetch has been started on it. The riser and spillway pipe appear to be in good shape. The berm is showing effects of wave erosion and would be improved by shaping with large stone.

Site #7 - Wilda - This dam has received much attention, such as brushhogging, Fall spraying for knapweed, Spring seeding of Ky 31, application of 10-10-10 fertilizer, and the owner will spot spray for weeds this growing season. The riser and pipe spillway appear to be in good shape, but the slide gate control rod and gate frame show much rust when the lake level is low.

Site #11 - Canada Run - County Dump - The woody growth was cut and sprayed last year. This dam should be mowed this year. The riser, pipe spillway and emergency spillway appear to be sound.

Site #24 - Happy Hollow Lake - This site has good vegetative cover and is kept mowed. The riser and pipe spillway appear sound. The emergency spillway is in good condition with good cover. The wooden trash rack is scheduled to be replaced.

Site #25 - Toms Branch - This dam has very little woody growth on it. The pipe spillway and emergency spillway are in good condition. Stone has been applied to the road on the dam and has improved the dam by eliminating the standing water on the top of the dam. This dam should be mowed in the next two years. The road banks above the dam (road going to Shirey camp) should be seeded to cut down the silt and erosion.

Wayne H. Hypes

APPENDIX V

EXCERPTS FROM GEOLOGY REPORT

GEOLOGY REPORT

SOUTH RIVER WATERSHED
COLD SPRINGS, SITE NO. 6
COLD SPRINGS, AUGUSTA COUNTY, VIRGINIA

GEOLOGY REPORT NO. VA-336-G

Prepared by: L. A. Gorman
Geologist, SCS,
Richmond, Virginia

Robert F. Fonner
Geologist, SCS, P. 21
S. C. S. Upper Sandy, R.

Introduction

General

State - Virginia; County - Augusta
Watershed - South River
Location - Cold Springs, 2 miles east of Greenville, Virginia
Explored by - L. A. Gorman, R. F. Fonner, Norman Wilson, and
French Hursey
Equipment used - Sprague and Henwood #40 Core Drill and tractor
mounted Backhoe

Site Data (Approximate)

Drainage Area 4.23 sq. mi. - 2,707 acres
Type of structure - Earthen Dam; Purpose - Conservation
Height of fill - 46 feet; Length - 1,400 feet
Volume of fill required - 148,000
Location of emergency spillway Left (West) abutment
Surface area of normal pool - 37 acres

Site No. 6, South River Watershed, is located about one mile east of Cold Spring Station on Cold Spring Branch. The headwaters originate from Cellar Mountain, elevation 3,645, flowing almost due north to the site, approximate elevation 1,590.

The original geologic investigation was made during the week of August 5, 1957 with the following SCS personnel participating: R. F. Fonner, geologist; Norman Wilson, engineer, and French Hursey, soil scientist. The pits were dug with a Shawnee backhoe mounted on a heavy duty farm tractor which dug to depths of approximately 12 feet.

After the results of the soil sample tests were received, it was decided that deeper investigations were necessary, to collect additional samples for tri-axial shear and time compaction tests. The Cunningham Core Drilling and Grouting Corp., Salem, Virginia, was awarded the contract to do the additional exploration. The drilling was done with a Sprague and Henwood #40 Core Rig during the period of November 13 - 22, 1957 under the supervision of L. A. Gorman, geologist, SCS, Richmond, Virginia.

The drilling was done using a carbide tipped bit for the softer materials and a diamond tipped core bit for the more consolidated sections and to core the bedrock. The hole size was standard NX. Sampling was accomplished by means of a push tube. Two length samples were taken,

REFERENCE:

U. S. DEPARTMENT OF AGRICULTURE
SOIL CONSERVATION SERVICE

DRAWING NO.
VA-336-G

SHEET 1 OF 20
DATE 1-16-58

GEOLOGY REPORT

SOUTH RIVER WATERSHED
COLD SPRINGS, SITE NO. 6
COLD SPRINGS, AUGUSTA COUNTY, VIRGINIA

one foot for the harder material and two foot samples for the softer material. The samples were sealed with wax and marked for later identification at the laboratory. Samples were to be taken at ten foot intervals but generally the material was too hard and therefore samples were taken wherever possible. A total of five samples were taken in the four holes drilled.

GEOLOGY AND PHYSIOGRAPHY

The area under consideration in this report is covered by alluvial material so no bedrock crops out in the vicinity of the structure site. The rocks which are present under the alluvium are of Cambrian and Ordovician age, these include the Waynesboro Formation, Elbrook Dolomite and the Conococheague Limestone (Fig. 1) These formations include shale, sandstone, limestone and dolomite which can weather into the type of clay deposits found in this vicinity.

The alluvium present in this valley is typical of the Piedmont alluvial terraces found in the Shenandoah Valley. Cold Spring is a subsequent stream superimposed upon this terrace material of weathered sandstone cobbles and gravel, sandy silts and clays. Its valley is over 60 feet deep and 1,100 feet wide with valley walls sloping 10 - 25 percent. The drainage pattern is dendritic.

CENTERLINE OF DAM

Along the centerline of the dam 10 test pits were made with the backhoe and 4 with the core drill. Test pits were dug along the centerline of the dam as follows:

East abutment - test pit Nos. EH-1
Valley floor - test pits Nos. EH-2, 3, 4, 5, and 6
West abutment - test pits Nos. EH-7, 8, 9, and 10

The four core drill holes were located as follows:

West abutment - CB-1
Valley floor - CB-2 and 3
East abutment - CB-4

The West abutment test hole CB-1 consisted of:

0 - 20' Yellowish brown clayey gravel with quartzite cobbles
20 - 21 Silty clay with gravel yellowish brown (Sample #15, 20-21')
21 - 30 Stratified silty clay (Very light weight) Chocolate brown
30 - 40 Stratified silty clay yellow brown, vertical bedding
(May be decomposed shale.)
40 - 50 Yellow brown silty clay-not as well stratified as above, some white streaks and specks.

REFERENCE:

U. S. DEPARTMENT OF AGRICULTURE
SOIL CONSERVATION SERVICE

DRAWING NO.
VA-336-G

SHEET 2 OF 20

DATE 1-16-58

G E O L O G Y R E P O R T

SOUTH RIVER WATERSHED
COLD SPRINGS, SITE NO. 6
COLD SPRINGS, AUGUSTA COUNTY, VIRGINIA

The holes located in the valley floor (CB-2 and 3) indicated the following:

- 0 - 10' Gravel with quartzite cobbles clay and sandy matrix
- 10 - 20 Clayey gravel Yellowish brown (too hard to sample)
- 20 - 30 Gravelly clay in layers (too hard to sample)
- 30 - 40 Gravelly clay, silty, stratified (horizontal)
- 40 - 50 Stratified silty clay - hard (bedding? vertical)
- 50 - 58 Stratified silty clay - some sand (Sample #17, 50-51.8')
- 58 - 64 Hard silty sand, brown
- 64 - 78 Stratified clay (may be decomposed shale) Vertical bedding yellow brown - Dark brown some black (Possibly organic material - Sample #18, 64-66')

The drill hole in the East abutment (CB-4) showed the following material:

- 0 - 10' Soil, Gravel with clay and sand
- 10 - 50' Gravelly clay and boulders (too hard to sample)

The foundation appears sound although further testing of the fine material below the gravelly layer should be done before any final decisions can be made. This softer material is probably decomposed shale which should supply an adequate foundation.

Conclusions:

1. The foundation appears adequate to support the structure.
2. The abutments appear sound, the material in the west abutment is very similar to the material found under the valley but that under the east abutment is of a more stable nature and no difficulty should be anticipated.
3. Some leakage could possibly take place along the valley but this could be taken care of by toe drains.

SPILLWAYS

The conditions under the proposed principal spillway are the same as the valley floor. Additional soil tests are being made. To prevent any difficulty it might be advantageous to relocate the principal spillway in the east abutment area where no appreciable settlement would take place. (See CB-4)

The emergency spillway is located on the west abutment according to BH-200, 201 the material can be removed by normal excavation methods. No bedrock was encountered.

Vegetal cover should be adequate for erosion control.

REFERENCE:

U.S. DEPARTMENT OF AGRICULTURE
SOIL CONSERVATION SERVICE

DRAWING NO.
VA-336-G

SHEET 3 OF 20
DATE 1-16-58

GEOLOGY REPORT

SOUTH RIVER WATERSHED
COLD SPRINGS, SITE NO. 6
COLD SPRINGS, AUGUSTA COUNTY, VIRGINIA

BORROW AREAS

Available borrow material can be found anywhere in the vicinity of the structure. For type of borrow material see EH 200, 201. The emergency spillway cut will supply a large amount of fill and the additional fill material can be found below Station 94 in both valley walls. It is strongly suggested that no borrow material be taken from the permanent pool area.

Selection of core material and suitable borrow material for the fill and drain will be determined from the laboratory tests.

CONCLUSIONS:

Further testing is necessary before final conclusions can be reached.

1. Adequate borrow material is available.
2. No bedrock was found in test pits in the emergency spillway, so normal methods of excavation should be adequate.
3. Erosion control of the emergency spillway can be achieved with proper vegetation and soil amendments.
4. Due to the fineness of the material in the valley fill, additional soil testing will be necessary before the adequacy of the foundation material can be determined.
5. No evidence of landslides, springs, or excessive seepage was noted.
6. Suggest locating the principal spillway in the east abutment area.
7. Strongly suggest no borrow material be removed from the permanent pool area.

SOIL SAMPLES


Disturbed soil samples were taken of each distinct horizon found throughout the site. Undisturbed samples were taken of the fine silty clay material in the valley fill. These samples were taken to the Virginia State Highway Soils Mechanics Laboratory, Charlottesville, Virginia, for testing. Push tube samples were taken during the core drilling and sent to the Soils Mechanics Laboratory at Lincoln, Nebraska and the results are pending.

As an aid to correlating the results of the tests with the location of the soil sample, the following table can be used.


REFERENCE:	U.S. DEPARTMENT OF AGRICULTURE SOIL CONSERVATION SERVICE	DRAWING NO. VA-336-G SHEET 4 OF 20 DATE 1-16-58
------------	---	--

13150 14150 15150 16150 17150 18150 19150

Geologic Report



Profile Along E Dam (Looking Downstream)
Showing Boring Locations
Scale 1" = 200'



Profile Valley X-Sections
Showing Boring Locations
Scale 1" = 200'

O Backhoe Holes
• Core Drill Holes

SITE No. 6 Cold Spring

3 5/8 E Dam
1150 1150

Profile Along E Pipe

Sheet B

Profiles & X-Sections shown looking Downstream
or to the RIGHT - Suck at the Conduit & V-5

VA-336-G 1/18/57

Form SCS-533
MAY 59

U.S. DEPARTMENT OF AGRICULTURE
SOIL CONSERVATION SERVICE

SOIL AND FOUNDATION INVESTIGATIONS
LOG OF BORINGS

Location Cold Springs Owner South River State VA Area Site No. 8
Watershed Potomac River Sub-watershed South River
Logged by R.E. Fennor, N.W. Wilson, F.W. Hurrey Date 8/5 & 6 1957 Project WPI WP2 FPX Pub. 46
Sampling Equipment Back Hoe Location of borings Centerline of Dam

Hole No.	Location & Surface Elev.	Hole Depth		Description of Material (note depth at which water occurs)	Sample No. & Type	Depth	
		From Ft.	To Ft.			From Ft.	To Ft.
BH-1	2/76 C/L 1598.6	0	2.6	Silty sand & gravel, brown			
		2.6	5.0	Gravels & cobbles, w/ass, in clayey sand matrix, loose			
		5.0	9.0	Gravels & cobbles, w/ass, imbedded in clayey sand, tight			
		9.0	11.0	Silty clay, red & yellow variegated, compact			
BH-2	4/50 o/L 1688.7	0	3.0	Clayey sand, brown			
		3.0	5.0	Cobbles & gravels, sandstone	2 D	6.0	13.0
		5.0	13.0	Clay, massive, red & yellow variegated, loaded w/mn conc. vert. seepage zone capped w/clay column struct.			
				Water at 10.3 Seepage thru mn pockets - Dauphin conc.			
BH-3	6/12 C/L 2/50 Con- duit 1690.1			Water at 10.5			
		0.0	5.5	Sand, gravel & cobbles	11 D	1.0	5.5
		5.5	11.0	Lt. silty clay yellow white variegated, in coating on root channels & seep planes			
		11.0	15.0	Very moist - high silt content at 11.0 to 16.0	12 D	5.5	11.0
		16.0	18.0	Clay silt, firm & dry	13 D	10.0	20.0
					17 Undist.	11.0	

Sheet / Color Sheets

Disturbed - undisturbed rock core. 1 Copy to E and WP unit. Distribute other copies as directed by State Conservationist

Form SCS-533
MAY 55

U.S. DEPARTMENT OF AGRICULTURE
SOIL CONSERVATION SERVICE

SOIL AND FOUNDATION INVESTIGATIONS
LOG OF BORINGS

Location Cold Springs State Va. Area
Watershed Potomac River Sub-watershed South River Site No. 6
Logged by R.F. Fanner, H.W. Wilson, F.W. Hursey Date 8/5/66 19 57 Project: WPI WP2 FP 1 Pub. 46
Sampling Equipment Back Hoe Location of borings Borrow Area

Hole No.	Location & Surface Elev.	Hole Depth		Description of Material (note depth at which water occurs)	Sample No. Type	Depth	
		From Ft.	To Ft.			From Ft.	To Ft.
BH-100	93/00 B.L.	0.0	2.0	Gravels in silty sand			
	200' L	2.0	6.5	Cobbles & gravels in silty sand	4	L	0.0 2.0
	1599.5	6.5	9.5	Cobbles & gravels in yellow silty clay	5	L	2.0 6.0
				Stiff, massive, heavy	6	L	7.0 9.5
BH-101	93/00 B.L.	0.0	2.0	Gravel in silty sand			
	1598.6	2.0	7.5	Cobbles & gravels in clayey sand			
		7.5	10.0	Stiff, heavy massive silty clay w/white streaks & pockets	7	L	7.5 10.0
BH-102	93/00 B.L.	0.0	5.5	Cobbles & gravels in silty sand			
1599.2	150' R	5.5	10.0	Silty sandy clay, stiff, heavy, massive slight varving at 10.0'			
BH-103	95/00 B.L.	0.0	7.0	Cobbles & gravels in silty sand			
	200 R	7.0	9.5	Yellow & brown silty clay w/scattered sand & small gravels			
	1597.2	8.5	10.0	Clayey silt, yellow, white, brown -varved -shear zones in contact.			

Sheet 1 of 20 Sheets

*Disturbed - undisturbed - rock core. 1 Copy to E and WP unit. Distribute other copies as directed by State Conservationist.

SOIL AND FOUNDATION INVESTIGATIONS

LOG OF BORINGS

Location Cold Springs
Watershed Potomac River
Logged by R.F. Fonner, J.M. Wilson, S.W. Harsey
Sampling Equipment Backhoe
Sub-watershed South River
Date 8/5 & 6 1954
Project WP1 WP2
Emergency Spillway
State Va.
Site No. C
Pub. 46

Hole No.	Location & Surface Elev.	Hole Depth		Description of Material (note depth of which water occurs)	Sample No.	Sample Type	Depth	
		From Ft.	To Ft.				From Ft.	To Ft.
1-BH-200	12400 C.L.	0.0	2.5	Gravally silty sand.				
	1450 D.S.	2.5	8.0	Fine sandy clay (sand cont. variable).	16	D	2.0	8.0
	1649.6	8.0	18.0	Lt. fine silty clay (yellow-red w/streaks of white).	17	D	8.0	12.0
1-BH-201	12400 C.L.	0.0	1.0	Silty sand (few fine gravel)				
	20' V.S.	1.0	5.0	Heavy silty clay w/white streaks.				
	1639.4	5.0	12.0	Lt. fine silty clay (silt variegated) (few white streaks).				

Sheet 14 of 20 sheets

Disturbed-undisturbed-rock core: 1 Copy to E and WP unit. Distribute other copies as directed by State Conservationist

Form SCS-533
MAY 55

U.S. DEPARTMENT OF AGRICULTURE
SOIL CONSERVATION SERVICE

SOIL AND FOUNDATION INVESTIGATIONS
LOG OF BORINGS

Location Cold Springs State Pa. Area
Watershed Potomac River Sub-watershed South River Site No.
Logged by R.F. Fournier, R.W. Wilson, F.W. Hursey Date 8/5 & 6 1957 Project: WPI WP2 FP X Pub. 46
Sampling Equipment Rock Ho Location of borings Borrow Area

Hole No.	Location & Surface Elev.	Hole Depth		Description of Material (note depth at which water occurs)	Sample		Depth	
		From Ft.	To Ft.		No.	Type	From Ft.	To Ft.
BH-104	95/00 B.L.	0.0	7.0	Cobbles & gravels in silty sand.				
	1593.6	7.0	10.5	Silty clay, stiff, heavy, massive - water at 9.5'.				
BH-105	No hole.							
BH-106	95/00 B.L.	0.0	2.0	Gravels in silty sand.				
	250' L	2.0	7.5	Cobbles & gravels in silty sand.				
	1599.0	7.5	10.0	Yellow silty clay, stiff, heavy, massive.				
	This hole hit the edge of an old stream channel where cobbles & gravels in silty sand went to 10.0'.							
BH-107	96/00 B.L.	0.0	3.0	Gravels in silty sand.	8	Y	0.0	3.0
	250' L	3.0	6.0	Cobbles & gravels in silty sand.	9	Y	3.0	6.0
	1598.9	6.0	8.5	Yellow silty clay, stiff, heavy, massive.	10	Y	6.0	10.5
		8.5	10.5	Yellow silty clay, stiff, heavy - some layering.				

Sheet 20 of 20 Sheets

Disturbed - undisturbed - rock core. 1 Copy to E and WP unit. Distribute other copies as directed by State Conservationist.

Form SCS-533
MAY 55

U.S. DEPARTMENT OF AGRICULTURE
SOIL CONSERVATION SERVICE
SOIL AND FOUNDATION INVESTIGATIONS
LOG OF BORINGS

Location Cold Springs State Pa. Area
Watershed Potomac River Sub-watershed South River Site No.
Logged by R.E. Fanner, H. W. Wilson, F. W. Eursay Date 8/5 & 6 1957 Project: WPI WP2 FP X Pub. 46
Sampling Equipment Brick Hog Location of borings Mechanical Spillway

Hole No.	Location & Surface Elev.	Hole Depth		Description of Material (note depth at which water occurs)	Sample No.	Type	Depth	
		From Ft.	To Ft.				From Ft.	To Ft.
BH-300	1410	0.0	2.0	Sand & gravels, loose.				
	1591.5	3.0	8.0	Cobbles & gravels in silty mud sand - mod compact.				
		8.0	10.0	Sandy clay w/small gravels, brown, black, yellow - See logs zone.				
		10.0	11.0	Ye white varved fine silty sand - slumped - very compact.				
BH-301	1475	0.0	2.5	Silty sand & small gravel, brown.				
	1592.1	2.5	5.0	Cobbles & gravel in silty sand - loose.				
		5.0	9.0	Ye br silty clay, compact w/black in core moist.				
		9.0	11.0	Ye white varved clayey silt, slumped, high moist content (undisturbed red).				
BH-302	3400	0.0	6.3	Cobbles & gravels in silty sand, brown.				
	1593.7	6.3	9.3	Clayey silt, ye red white black variegated - slight varving at bottom.				
BH-303	4410	0.0	4.6	Cobbles and gravels in silty sand, brown.				
	1596.9	4.6	9.5	Ye & red silty clay variegated, varving at 7.5, massive.				

Sheet 15 of 20 Sheets

Disturbed - undisturbed - rock core. 1 Copy to E and WP unit. Distribute other copies as directed by State Conservationist

Form SCS-533

MAY 55

U. S. DEPARTMENT OF AGRICULTURE

SOIL CONSERVATION SERVICE

SOIL AND FOUNDATION INVESTIGATIONS
LOG OF BORINGS

Location Cold Springs State Vn. Area 6
 Watershed Potomac River Sub-watershed South River Site No. 6
 Logged by R. F. Penner, H. W. Wilson, F. W. Hursey Date 8/5 & 6 19 57 Project WPI WP2 FP 1 Pub. 46
 Sampling Equipment Hack Hoe Location of borings Centerline of Dam

Hole No.	Location & Surface Elev.	Hole Depth		Description of Material (note depth of which water occurs)	Sample No.	Type	Depth	
		From	To				From	To
		Fl.	Fl.				Fl.	Fl.
BH-7	10400 C/L	0.0	1.0	Gray, silty sand				
	1616.8	1.0	5.0	Clayey fine sand few scattered gravels & cobbles				
		5.0	8.5	Lt. silty clay (sand variable), streaks of white				
		8.5	10.5	Lt. fine silty clay (silt variable) liberally streaked w/ whitish material				
BH-8	11400 C/L	0.0	1.0	gravelly silty sand				
	1637.9	1.0	4.0	Heavy silty clay (sand content variable)				
		4.0	11.0	Lt. fine silty clay yellowish streaked with white				
BH-9	12400 C/L	0.0	1.0	gravelly silty sand				
	1648.8	1.0	5.0	Gravels & cobbles, comp. w/lt. fine sandy clay				
		5.0	11.0	Yellowish - red variegated lt. silty clay w/white streaks				
BH-10	13400 C/L	0.0	2.0	Gravels in silty sand				
	1655.7	2.0	9.0	Gravels & cobbles in loose clayey sand	14	D	2.0	9.0
		9.0	12.0	Heavy silty clay w/streaks of white	16	D	9.0	12.0

Sheet 1 of 20 Sheets

Disturbed - undisturbed rock core. 1 Copy for E and WP unit. Distribute other copies as directed by State Conservationist.

U. S. DEPARTMENT OF AGRICULTURE
SOIL CONSERVATION SERVICE

SOIL AND FOUNDATION INVESTIGATIONS

LOG OF BORINGS

Location 2 miles East of Greenville Owner _____ State _____ Area _____
 Watershed South River Sub watershed Cold Springs Site No. 6
 Logged by L. A. Gorman Date 11/26 19 57 Project: WPI _____ WP _____ Pub. 46
 Sampling Equipment: Sprague & Henwood #40 Core Rig (Skid) Location of borings 9 + 82 Near Spillway on left abutment

Hole No.	Location and Surface Elev.	Hole Depth		Description of Material (note depth at which water occurs)	Type of Bit used	Sample No.	Sample Type	Depth	
		From Ft.	To Ft.					From ft.	To ft.
CA-1	1612.7	0	10	Soil, Yellow Brown Clayey Gravel, Quartzite Cobbles	Drive Pipe				
	"	10	20	" " " "					
		20	21	Silty Clay with gravel Yellowish Brown		15	Push Tube	20	21
		21	30	Stratified silty clay (Very light weight) Chocolate Brown					
		30	40	Stratified silty clay Yellow Brown vertical bedding					
				May be decomposed shale.					
		40	50	Yellow brown silty clay - not as well stratified as above, some white streaks and specks.					
				Hole bottomed @ 50'					

Sheet 17 of 20 - Sheet 17

Form SCS-533

Rev. Feb. 56

U. S. DEPARTMENT OF AGRICULTURE

SOIL CONSERVATION SERVICE

SOIL AND FOUNDATION INVESTIGATIONS

LOG OF BORINGS

Location 2 miles East of Greenville

Watershed South River

Sub-watershed Cold Springs

State Va.

Area

Site No. 6

Logged by L. A. Gorman

Date 12/25

Project: WPI

WP2

FP X

Pub. 46

Sampling Equipment Sprague & Henwood #40 Core Rig (Skid)

Location of borings 7 + 50 On E of Dam left side of floodplain looking down stream

Hole No.	Location and Surface Elev.	Hole Depth		Description of Material (note depth at which water occurs)	Type of Bit used	Sample		Depth	
		From Ft.	To Ft.			No.	Type	From ft.	To ft.
CA-2	1594	0	10	Soil, clayey gravel yellow brown	Drive Pipe				
		10	20	Clayey gravel					
		20	21	Silty clay some gravel yellow brown, stratified with black streak and specks		13	Push Tube	20	21
		21	30	Silty clay stratified, vertical bedding, brownish yellow with white specks (may be decomposed shale)					
		30	31	Stratified silty clay vertical bedding (may be decomposed shale)		14	"	30	31
		31	40	Same as above					
		40	50	Yellow brown silty clay - some black along bedding planes (looks like decomposed shale)					
				Hole bottomed at 50'					

Sheet 18 of 20 Sheets

Disturbed undisturbed rock core. 1 Copy to E and WP unit. Distribute other copies as directed by State Conservationist.

U. S. DEPARTMENT OF AGRICULTURE
SOIL CONSERVATION SERVICE

SOIL AND FOUNDATION INVESTIGATIONS

LOG OF BORINGS

Augusta County - 2 miles East of Greenville

South River

Cold Springs

ya.

Area

Site No. 6

Logged by L. A. (Norman)

1957

X

Pub 15

Sprague & Henwood #140 Corp. Rig.: (Skld)

•

1

floodplain

Sampled Fulcrum
Sprague & Henwood #40 Core Rig: (Skid)

Location of business

Hole No.	Location and Surface Elev.	Hole Depth		Description of Material (note depth at which water occurs)	Type of Bit used	Sample		Depth	
		From	To			No.	Type	From	To
		ft.	ft.					ft.	ft.
	1500.8	0	10	Gravel Cobbles (Quartzite) some clay & sand matrix	Diamond				
		10	20	Clayey Gravel (Brown)(Yellowish)(Tried to sample 20" Too much gravel)					
		20	30	Gravelly clay in layers (Too hard to sample)					
	1502.3	30	40	Gravelly clay (silty clay stratified) Too hard to sample (Hazen #2)					
		40	50	Stratified silty clay - hard (bedding ? vertical)					
		50	58	Stratified silty clay - some sand		17	TYPE	50	51.8
		58	64	Harder silty sand Brown					
		64	66	Stratified clay may be decomposed shale (Vertical)		18	"	64	66
				Yellow Brown - Dark brown some black (Possible vegetable matter)					
		66	78	Same as above - too hard to sample					
				Bottomed hole					

SOIL AND FOUNDATION INVESTIGATIONS

LOG OF BORINGS

2 miles East of Greenville Station

South River Watershed

Owner _____
Sub-watershed _____

Cold Springs

va.

Are

5

Site No.:

Pub. 46

Logged by _____ Driller _____

Date:

11/27

15

Project: WFL

fp.

X

Location of borings 2 + 05 E of Dam light Abutment

[illegible]

Sheet 312 of 29 sheets

APPENDIX VI

DESIGN REPORT

DESIGN REPORT

SOUTH RIVER SUBWATERSHED
COLD SPRINGS, SITE NO. 6
COLD SPRINGS, AUGUSTA CO., VIRGINIA

Site 6, South River Subwatershed is located in the Shenandoah Valley about one mile east of Cold Spring Station on Cold Spring Branch.

The geographic location of this site may be found on the Vesuvius Quadrangle, published by the U. S. Geological Survey, by scaling 2-7/16 inches right (longitude 79° 37' 22" west) and 5-3/16 inches up (latitude 37° 53' 28" north) from the lower left hand corner of the quadrangle. Sheet 3 of this report is a transparent overlay that can be used to locate the proposed dam. By placing this overlay on the appropriate latitude and longitude lines on the Vesuvius Quadrangle, the location of the proposed dam may be found.

The purpose of this detention reservoir is to reduce flood flow in and around the town of Waynesboro and other points along the stream.

The dam has a watershed of 2708 acres. It is to be constructed of compacted earth on alluvial terrace material over silty clay. The principal spillway will be a drop inlet spillway with a reinforced concrete cylinder pipe, 24 inches inside diameter, and a reinforced concrete riser. It is to rest on silty clay. Maximum settlement is predicted to be 1.0'.

The riser is to be 3.0'x3.0' inside dimensions. An emergency spillway will also be provided which is to be cut into silty sand and clay on the west abutment.

The elevation of the sediment pool is based on the assumption that sediment will accrue in the reservoir area at the rate of 0.604 acre-feet per year. This assumption caused the level of the sediment pool to be set at an elevation of 1601.5. This elevation is the crest elevation of the principal spillway riser.

The flood routing procedure used in the design is described in Engineering Handbook, Section 5, Hydraulics, U. S. Department of Agriculture, Soil Conservation Service.

The flood routing procedure was used to determine the maximum stages shown in the table below.

REFERENCE	U. S. DEPARTMENT OF AGRICULTURE SOIL CONSERVATION SERVICE ENGINEERING & WATERSHED PLANNING UNIT UPPER DARBY, PENNSYLVANIA	DRAWING NO VA-336-R SHEET <u>1</u> OF <u>3</u> DATE <u>6-20-58</u>
-----------	--	---

DESIGN REPORT

Factor Which De-termines Stage	Surface Area Acres	Runoff in Inches	Peak Flow in CFS	Elev. of Max. Stage	Storage in Ac.-Ft.	Element of Structure Determined by Maximum Stage
50 year sedi-ment deposit	6.5				30.2	Crest of riser
100 year fre-quency storm		3.96	2120	1634.2	820	Crest of emergency spillway
1 x6 hour pt. rainfall, moisture condition III		9.56	4990	1639.7	1102	Design high water

A freeboard of 2 feet was selected. This freeboard was added to the distance from the crest of the 1 x 6 hour point rainfall and moisture condition III, to determine the top of the dam, elevation 1642.0.

The reinforced concrete design procedure was based on Engineering Handbook, Section 6, Structural Design, U. S. Department of Agriculture, Soil Conservation Service. The data used were for class B concrete as described in this publication.

The inflow hydrographs for the 100 year storm and the 1 x 6 hour point rainfall, moisture condition III, are constructed by the method described in Section 3.21 of the Hydrology Guide.

A copy of the Geology Report (VA-336-G) is attached.

Copies of Sections 5 and 6 of the Engineering Handbook and Section 3.21 of the Hydrology Guide may be obtained from Mr. Frank A. Edminster, State Conservationist, USDA, SCS, Richmond, Virginia.

Glenn W. Grubb
Design and Construction Engineer

Concurred:

Vincent McKeever
Hydrologist

Robert F. Fonner
Geologist

REFERENCE

U. S. DEPARTMENT OF AGRICULTURE
SOIL CONSERVATION SERVICE
ENGINEERING & WATERSHED PLANNING UNIT
UPPER DARBY PENNSYLVANIA

DRAWING NO.

VA-336-R
SHEET 2 OF 3
DATE 6-20-58

APPENDIX VII

EXCERPTS FROM DESIGN CALCULATIONS

Cold Springs, Site # 6

Ca 336-4
sheet 1 of 11

From Mass Rainfall Curve - 100 yr. Storm
where $f = 0.30$ "/hr. $(I-f)_{avg} = 3.96$ "

From Hydrology Sec., Suppl. A, NEH 4

$$P_c = 13.0$$

$$D.A. = 2708 A_c = 4.23 \text{ sq. mi.}$$

Modification factor, Fletcher = 0.90

$$P_m = 13.0 \times 0.90 = 11.70$$

Moderate Hazard Coeff. = 1.0

T_c (From Mockus Information) = 4.1 hrs.

$$T_p = \frac{AD}{2} + 0.6 T_c$$

$$T_b = 2.67 T_p$$

$$q_r = \frac{494 A Q}{T_p}$$

Total distance of water travel in watershed = 20,000 ft.

Difference in elev. = 2,000 ft.

1) 100 G Cold Springs

1/2-33-4

Sheet 2 of 11

REVISED COMPUTATION OF SUBHYDROGRAPH PEAKS TO
 SET CREST OF EMERGENCY SPILLWAY

MODERATE HAZARD CURVE 65 FOR MOISTURE CONDITION II

(I-F) = 3.96" $T_b = 4.1$ Hrs. $T_c = 2.71$ $T_d = 7.24$ $q_p = 754$ AD = 0.5 hr.

① Time (hrs)	③ Factors From Curve B	② Accumul. P (inches)	④ Accumul. Q (inches)	⑤ ΔQ (inches)	⑥ p o Q ③ x 754 (cfs)	⑦ starting time (hrs)	⑧ Peak time ⑦ + 2.71 (hrs)	⑨ Ending time ⑧ + 7.24 (hrs)
0.0	0.0	0.00	0					
				0.0	0	0.0	2.71	7.24
0.5	0.035	0.28	0					
				0	0	0.5	3.21	7.74
1.0	0.080	0.65	0					
				0	0	1.0	3.71	8.24
1.5	0.135	1.09	0					
				0.10	75.4	1.5	4.21	8.74
2.0	0.220	1.86	0.10					
				1.48	1115.9	2.0	4.71	9.24
2.5	0.600	4.86	1.58					
				0.56	422.2	2.5	5.21	9.74
3.0	0.705	5.71	2.14					
				0.46	346.8	3.0	5.71	10.24
3.5	0.780	6.32	2.60					
				0.32	241.3	3.5	6.21	10.74
4.0	0.835	6.76	2.92					
				0.31	233.7	4.0	6.71	11.24
4.5	0.885	7.17	3.23					
				0.25	188.5	4.5	7.21	11.74
5.0	0.925	7.49	3.48					
				0.25	211.1	5.0	7.71	12.24
5.5	0.965	7.82	3.76					
				0.20	150.8	5.5	8.21	12.74
6.0	1.000	8.10	3.96					

512-125

SET CAPACITY OF EMERGENCY SPILLWAY

MANAGERIAL - CURVE \pm 43.1 OUT. C.W.O. III $T_1 = 4.1$ $T_2 = 2.96$ $T_3 = 7.50$ $\Delta D = 1.6$
 $S_F = 690.23$ $R = 11.70$

[illegible]

5/3/1

DAM No 6 - COLD SPRINGS


WEIR FLOW

$$Q = CLH^{3/2}$$

$$C = 3.4$$

$$L = 12.0$$

$$Q = 40.8 \text{ HFS}$$



PIPE FLOW

$$Q_p = C_p H_p^{5/2}$$

$$C_p = A_p \sqrt{\frac{2g}{1 + K_r + K_p \frac{l_p}{d} + K_c \frac{l_r}{A_r} \left(\frac{A_p}{A_r}\right)^2}}$$

$$K_r = 1.45$$

$$\eta = 0.011$$

$$d = 24"$$

$$l_p = 287$$

$$A_p = 3.142$$

$$A_r = 9.0$$

$$S_p = 0.01045$$

$$K_p = 0.00283$$

$$\text{Assume } K_c \frac{l_r}{A_r} \left(\frac{A_p}{A_r}\right)^2 = 0$$

$$\left(\frac{A_p}{A_r}\right)^2 = \left(\frac{3.142}{9.0}\right)^2 = (0.3491)^2 = 0.1219$$

$$C_p = A_p \sqrt{\frac{64.32}{1 + 7.115 + 2.32 + 0}} = A_p \sqrt{\frac{64.32}{11.77}} = A_p \sqrt{13.4542}$$

$$= 3.14 \times 3.67 = 11.52$$

$$Q_p = 11.52 \text{ HFS}$$


5/26/57

$$b = 150' \quad z = 3 \quad L = 180'$$

Least at Elev. 1635.0 $n=0.04$

6-16-58

353 11 KESSEL & PETERSON CO.
10 X 10 to the 1/2 inch 6th line centered.
MADE IN U.S.A.



5. MECHANICAL SPILLWAY DISCHARGE

VII-7

Page 11

11-11-11
5-11

11-11-11
11/11/11

FOR FLOW OF 3200 (MAX FLOW) IN EMERGENCY

SPILLWAY, $d_c = 2.37 \text{ ft}$ AND $W' = 157.10 \text{ ft}$
 $Q_c = 20.37 \text{ cfs}$ AND $S_c = 0.0177$
 $n = 0.040$

FOR 25% MAX. FLOW OR 800 CFS.

$d_c = 0.94 \text{ ft}$ AND $W' = 152.20$
 $Q_c = 5.24 \text{ cfs}$ AND $S_c = 0.0239$
 $n = 0.040$

AN EXIT SLOPE OF 0.030 IN EMERGENCY
SPILLWAY WILL BE SATISFACTORY.


Cold Springs #6
V₀ = 33' - 0"

H.L.W.
5/20/58
Sheet 1 of 8

Riser Design

$$Ht. of riser = 1601.5 - 1592.4 = 9.1'$$

Assume water 2' over crest of riser & riser empty.
No earth pressure



$$V_0 = \frac{1}{2} q l_c = \frac{692.6 \times 3}{2} = 1038.9'$$

d required = Less than 3"

Use 1" effective 7.5" Total d = 70"

$$Then M (end) = \frac{1}{12} q l^2 = \frac{692.6 \times 3.03^2}{12} = 846.6'$$

A_s (required) = Less than 0.10"

Use Temperature steel

All Horizontal #4 @ 15" Use #4 @ 12"

All Vertical #5 @ 15"

6-17-58
Gm

EA 0777

HYDROGRAPH COMPUTATION

DATE _____
COMPUTED BY _____
CHECKED BY _____

WATERSHED OR PROJECT SOUTH RIVER

STATE VIRGINIA

STRUCTURE SITE OR SUBAREA 6

DR. AREA 4.23 SQ. MI. STRUCTURE CLASS C

T_c 4.1 HR. STORM DURATION 6 HR.

POINT RAINFALL 11.88 IN.

ADJUSTED RAINFALL:

AREAL: FACTOR — IN. —

DURATION: FACTOR — IN. —

RUNOFF CURVE NO. 65

Q 6.96 7.15 IN.

HYDROGRAPH FAMILY NO. 32

COMPUTED T_p 2.87 HR.

T_0 4.30 1.71 HR.

(T_0 / T_p) : 50
COMPUTED 1.64 ; USED 1.5

REVISED T_p 3.27

$q_c = \frac{484A}{REV. T_p} = \frac{484 \times 4.23}{3.27} = 626$ CFS.

$(Q \times q_p) = \frac{484 \times 11.88}{3.27} = 475$ CFS.

$U(COLUMN) = (1 / T_p) REV. T_p$ $q(COLUMN) = (q_c / q_p) \times Q \times q_p$

$Q(COLUMN) = (Q_t / Q) Q$

	$t = (t/T_p) REV. T_p$	$q = (q_c / q_p) (Q \times q_p)$	$Q_t = (Q_t / Q) Q$
	t HOURS	q CFS	Q INCHES
1	0	0	0
2			
3			
4			
5			
6	6.00	3556	
7			
8	5.04	3556	
9			
10			
11			
12			
13			
14			
15			
16			
17			
18			
19			
20			
21			
22			
23			
24			
25			
26			
27			
28			
29			
30			
31			
32			
33			
34			

FEDERAL BUREAU OF SURVEY
UNITED STATES DEPARTMENT OF AGRICULTURE
NATIONAL ENGINEERING SERVICE
METHOD OF RESERVOIR FLOOD ROUTING

State INDIANA Watershed W. 1TH R. VGL. Site C
Class C $V_{us} =$ AF $V_{ub} =$ AF $V_{ud} =$ AF $V_{u} =$ AF


Storm Eq. 5 p. 14 DA 11.23 mi² Runoff 7.15 in. $C_1 =$ 3736
Hydrograph Family 2 T_o/T_p 1.5 $V_1 = 53.33 \times \text{Runoff} \times D.A. =$ 16.13

$Q_1 =$ cfs $E_n =$ ft $V_{sf} =$ AF $V_{sf}/V_1 =$
 $Q_1/Q_2 =$ $V_{th} =$ AF $V_{sf}/V_1 =$ $V_{sf}/V_1 =$

$E_e =$ 1635.0 ft $z =$ 3 $L =$ 150 ft $V_{sf}/V_1 =$ 0.526
 $V_{1e} =$ AF Case 2 $S_o =$ 2% $V_{sf}/V_1 + V_{sf}/V_1 =$
 $V_{sf} =$ 553 AF $Q_h =$ 62.4 cfs $V_{sf}/V_1 =$ 0.542
 $Q_{pl} =$ 78 cfs $Q_1/Q_2 =$ 0.6177 $V_{sf}/V_1 =$ 0.614

1	2	3	4	5	6	7	8	9	10	11	12
E_w ft	V_{1w} AF	V_{sw} AF	V_{sw}/V_1	V'_{sw}/V_1	Q_0/Q_1	Q_0 cfs	Q_e cfs	H_p ft	Q_e/b	b ft	v fps
1637.0		955	0.592	0.606	0.73	2620	2542	2.0	6.15	414	
1637.5		960	0.606	0.62	0.69	2450	2322	2.5	4.55	293	
1638.0		1007	0.624	0.639	0.63	2225	2147	3.0	12.00	170	
1638.5		1035	0.642	0.656	0.58	2042	1964	3.5	16.00	118	

Maximum Water Surface Elevation (E_w) - ft.



Velocity (V) - fps

VII-11
Emergency Spillway Width (b) - ft.

HYDROGRAPH COMPUTATION		DATE _____	
		COMPUTED BY _____	
		CHECKED BY _____	
WATERSHED OR PROJECT <u>SOUTH RIVER</u>		$t = (1/T_p) \text{Rev. } T_p$	$q = (q_c / q_p) (QXq_p)$
STATE <u>VIRGINIA</u>		$Q_t = (Q_t / Q)Q$	
STRUCTURE SITE OR SUBAREA <u>#6</u>		1	0
DR. AREA <u>4.23</u> SQ. MI. STRUCTURE CLASS <u>C</u>		HOURS	q CFS
T_c <u>4.1</u> HR. STORM DURATION <u>6</u> HR.		INCHES	
POINT RAINFALL <u>13.0</u> IN.		1	0
ADJUSTED RAINFALL:		2	
AREAL : FACTOR <u>0.9</u> IN. <u>11.7</u>		3	
DURATION : FACTOR _____ IN. _____		4	
RUNOFF CURVE NO. <u>83</u> M.C. III		5	
Q <u>9.56</u> IN.		6	<u>2100</u> <u>4545</u>
HYDROGRAPH FAMILY NO. <u>1</u>		7	
COMPUTED T_p <u>2.87</u> HR.		8	
T_o <u>5.50</u> HR.		9	
(T_o / T_p) : COMPUTED <u>1.92</u> ; USED <u>2.0</u>		10	
REVISED T_p <u>2.75</u>		11	
$q_p = \frac{484A}{\text{REV. } T_p} = \frac{744}{\text{REV. } T_p}$ CFS.		12	
$(QXq_p) = \frac{6914}{\text{REV. } T_p}$ CFS.		13	
$q(\text{COLUMN}) = (1/T_p) \text{REV. } T_p$ $q(\text{COLUMN}) = (q_c / q_p) (QXq_p)$		14	
$Q(\text{COLUMN}) = (Q_t / Q)Q$		15	
		16	
		17	
		18	
		19	
		20	
		21	
		22	
		23	
		24	
		25	
		26	
		27	
		28	
		29	
		30	
		31	
		32	
		33	
		34	

METHOD OF RESERVOIR FLOOD ROUTING


Storm W. 100 yr. Watershed 1,000 sq. mi. Site C
Class C $V_{us} =$ AF $V_{ud} =$ AF $V_{ud} =$ AF $V_{ul} =$ AF

Storm: EN. S.W. 1 D.A. 4.23 mi.² Runoff 9.56 in. $Q_1 =$ 3645 cfs
Hydrograph Family 1 T_0/T_p 2.0 $V_1 = 53.33 \times \text{Runoff} \times \text{D.A.} =$ 2127 cfs

$Q_1 =$ cfs $E_h =$ ft $V_{s2} =$ AF $V_{s2}/V_1 =$
 $Q_1/Q_2 =$ $V_{th} =$ AF $V_{s1}/V_1 =$ $V_{s1}/V_1 =$

$E_e =$ 1637.0 ft $z =$ 3 $L =$ 150 ft $V_{sp}/V_1 =$ 0.346
 $V_{1e} =$ AF Case 2 $S_0 =$ 2% $V_{sp}/V_1 =$
 $V_{sp} =$ 853 AF $Q_h =$ 62.4 cfs $V_{sp}/V_1 =$ 0.401
 $Q_{ph} =$ 75 cfs $Q_h/Q_1 =$ 0.0115 $V_{op}/V_1 =$ 0.005

1	2	3	4	5	6	7	8	9	10	11	12
E_w ft	V_{1w} AF	V_{sw} AF	V_{sw}/V_1	V'_{sw}/V_1	Q_0/Q_1	Q_0 cfs	Q_e cfs	H_p ft	Q_e/D	D ft	v fps
1838.0		1007	0.468	0.473	0.55	4790	4712	3.0	12.6	375	
1832.5		1035	0.481	0.486	0.62	4625	4542	3.5	16.6	273	
1837.0		1060	0.492	0.497	0.80	4510	4432	4.0	21.0	211	
1831.5		1090	0.506	0.511	0.76	4290	4212	4.5	25.5	167	
1840.0		1116	0.517	0.522	0.73	4120	4042	5.0	31.0	133	



FREEDMAN HYDROGRAPH COMPUTATION

DATE _____
COMPUTED BY _____
CHECKED BY _____

WATERSHED OR PROJECT SOUTH RIVER

STATE VIRGINIA

STRUCTURE SITE OR SUBAREA 6

DR. AREA 4.23 SQ. MI. STRUCTURE CLASS C

T_c 4.1 HR. STORM DURATION 6 HR.

POINT RAINFALL 27.3 IN.

ADJUSTED RAINFALL:

AREAL: FACTOR _____ IN. _____

DURATION: FACTOR _____ IN. _____

RUNOFF CURVE NO. 65

Q 21.75 IN.

HYDROGRAPH FAMILY NO. 1

COMPUTED T_p 2.87 HR.

T_o 5.45 HR.

(T_o/T_p) :
COMPUTED 1.89 USED 2.00

REVISED T_p 2.72

$q_p = \frac{484A}{REV. T_p} = \frac{484 \times 4.23}{2.72} = 770.753$ CFS.

$(QXq_p) = \frac{15763}{16.378}$ CFS.

$(COLUMNS) = (t/T_p) REV. T_p$ $(COLUMNS) = (q_c/q_p) QXq_p$

$Q(COLUMNS) = (Q_t/Q)Q$

	$t = (t/T_p) REV. T_p$	$q = (q_c/q_p) QXq_p$	$Q_t = (Q_t/Q)Q$
	HOURS	CFS	INCHES
1	0	0	0
2			
3			
4			
5			
6	<u>2.72</u>	<u>12.524</u>	
7	2.72	12.524	
8			
9			
10			
11			
12			
13			
14			
15			
16			
17			
18			
19			
20			
21			
22			
23			
24			
25			
26			
27			
28			
29			
30			
31			
32			
33			
34			

UNITED STATES DEPARTMENT OF AGRICULTURE BUREAU OF RECLAMATION DESIGN OF EARTH EMBANKMENT DAMS AND METALLIC RESERVOIR FLOOD PROTECTORS


State Ill. Watershed Ill. River Site Ill.
Class C $V_{uc} =$ AF $V_{uc} =$ AF $V_{uc} =$ AF $V_{uf} =$ AF

Storm 10500000 D.A. 4.25 mi² Runoff 21.77 in. $C_1 =$ 12.130 cfs
Hydrograph Family 1 T_o/T_p 2.00 $V_1 = 53.33 \times \text{Runoff} \times \text{D.A.} =$ 4907 AF

$Q_1 =$ cfs $E_n =$ ft $V_{s2} =$ AF $V_{s2}/V_1 =$
 $C_2/Q_1 =$ $V_{th} =$ AF $V_{s2}/V_1 =$ $V_{ol}/V_1 =$

$E_e =$ 1635.0 ft $z =$ 3 $L =$ 150 ft $V_{sp}/V_1 =$ 0.174
 $V_{ie} =$ AF Case 2 $S =$ 2% $V_{sp}/V_1 + V_{ol}/V_1 =$
 $V_{sp} =$ 553 AF $Q_n =$ 62.4 cfs $V_{sp}/V_1 =$ 0.175
 $Q_{ph} =$ 78 cfs $Q_n/Q_1 =$ 0.00514 $V_{ol}/V_1 =$ 0.004

1	2	3	4	5	6	7	8	9	10	11	12
E_w ft	V_{1w} AF	V_{sw} AF	V_{sw}/V_1	V'_{sw}/V_1	Q_o/Q_1	Q_o cfs	Q_e cfs	H_p ft	Q_e/b	b ft	v fps
1641.		1165	0.235	0.242	0.93	11875	11500	6.0	42.2	240	
1641.5		1175	0.244	0.248	0.97	11750	11675	6.5	43.5	240	
1642.0		1220	0.245	0.252	0.97	11750	11675	7.0	55.0	213	
1642.5		1256	0.262	0.266	0.96	11636	11558	8.0	75.0	165	
1642.5		1275	0.260	0.264	0.95	11514	11436	7.5	62.5	153	
1642.5		1314	0.265	0.272	0.96	11636	11555	8.5	76.5	152	
1642.5		1345	0.274	0.278	0.95	11514	11436	9.0	85.0	134	



VII-15
Emergency Spillway Width (b) - ft.

HYDROGRAPH COMPUTATION

DATE _____
COMPUTED BY _____
CHECKED BY _____

WATERSHED OR PROJECT SOUTH RIVER

STATE VIRGINIA

STRUCTURE SITE OR SUBAREA 6

DR. AREA 4.23 SQ. MI. STRUCTURE CLASS C

T_c 4.1 HR. STORM DURATION 6 HR.

POINT RAINFALL 27.3 IN.

ADJUSTED RAINFALL:

AREAL: FACTOR _____ IN. _____

DURATION: FACTOR _____ IN. _____

RUNOFF CURVE NO. 65

Q 21.75 IN.

HYDROGRAPH FAMILY NO. 2

COMPUTED T_p 2.87 HR.

T_o 5.45 HR.

(T_o / T_p) :
COMPUTED 1.90; USED 2.00

REVISED T_p 2.72

$q_p = \frac{484A}{REV. T_p} = \underline{793}$ CFS.

$(QXq_p) = \underline{76378}$ CFS.

$\alpha(COLUMN) = (t / T_p) REV. T_p$ $\alpha(COLUMN) = (q_c / q_p) QXq_p$

$Q(COLUMN) = (Q_t / Q)Q$


	$t = (1/T_p) Rev. T_p$	$q = (q_c / q_p) QXq_p$	$Q_t = (Q_t / Q)Q$
	t HOURS	q CFS	Q INCHES
1	0	0	0
2			
3			
4			
5			
6			
7	4.57	11,710	
8			
9			
10			
11			
12			
13			
14			
15			
16			
17			
18			
19			
20			
21			
22			
23			
24			
25			
26			
27			
28			
29			
30			
31			
32			
33			
34			


1A FORMER K. J. B. L. SOUTH RIVER 6
 C $V_1 =$ $V_2 =$ $V_3 =$ $V_4 =$
 EM. SPWY. D.A. 4.25 \times 2 Runoff 6.70 in. $O_1 = 2831$
 Hydrograph Family 2 $T_c = 1.5$ $V_1 = 53.33 \times \text{Runoff} \times \text{D.A.} = 1511$

$Q_1 =$ cfs $E_b =$ ft $V_{s2} =$ AF $V_{s1}/V_1 =$
 $Q_2/Q_1 =$ $V_{s1} =$ AF $V_{s2}/V_1 =$

$E_b = 1635.0'$ $z = 3$ $L = 150'$ $V_{sp}/V_1 = 0.964$
 $V_{s1} =$ AF Case 2 $S_0 = 3\%$ $V_{sp}/V_1 =$
 $V_{sp} = 853$ AF $C_n = 62.4$ cfs 553 $V_{sp}/V_1 = 0.531$
 $Q_{s1} = 78$ cfs $Q_1/Q_2 = 0.022$ $V_{s1}/V_1 = 0.024$

	2	3	4	5	6	7	8	9	10	11	12
E_w ft	V_{sw} AF	V_{sw} AF	V_{sw}/V_1	V_{sw}/V_1	Q_0/Q_1	Q_0 cfs	C_e cfs	H_p ft	C_e/D	L ft	L/D
1636.0		900	0.596	0.628	0.75	2122	2044	1	1.85	1435	1523
1637.0		954	0.631	0.655	0.65	1840	1762	2	6.18	288	343
1637.5		982	0.650	0.672	0.58	1621	1563	2.5	9.20	170	204
1638.0		1005	0.665	0.682	0.56	1557	1499	3.0	12.60	147	143





HYDROGRAPH COMPUTATION

ET SPRAY

WATERSHED OR PROJECT POTOMAC RIVER SOUTH RIVER STATE VA

STRUCTURE SITE OR SUBAREA 6 COLF SPRINGS

DR. AREA 4.23 SQ. MI. T. 4.1 HR. CLASS "C" RUNOFF CONDITION NO. II

RUNOFF CURVE NO. 65 STORM DISTRIB. CURVE B HYDROGRAPH FAMILY NO. 2

STORM DURATION 6 HR. RAINFALL: 0.7 TC POINT 11.3 IN. AREAL 11.3 IN.

Q 6.70 IN. COMPUTED T, 2.87 HR. T. 4.83 HR.

(T₀ + T_p) COMPUTED 1.68 USED 1.5 REVISED T, 3.22

$q_p = \frac{484 A}{REV. T_p} = \frac{484 \times 4.23}{3.22} = 636$ CFS. $Q_p = \frac{4361}{3584}$ CFS.

(C COLUMN) = (1/T_p) REV. T_p (C COLUMN) = (q_p/Q_p) Q_p

LINE NO.	T HOURS	Q CFS	LINE NO.	T HOURS	Q CFS	LINE NO.	T HOURS	Q CFS
1			21			41		
2			22			42		
3			23			43		
4			24			44		
5			25			45		
6			26			46		
7			27			47		
8	<u>1.72</u>	<u>2831</u>	28			48		
9			29			49		
10			30			50		
11			31			51		
12			32			52		
13			33			53		
14			34			54		
15			35			55		
16			36			56		
17			37			57		
18			38			58		
19			39			59		
20			40			60		

APPENDIX VIII

GENERAL REFERENCES

GENERAL REFERENCES

1. Bureau of Reclamation, U.S. Department of the Interior, Design of Small Dams, A Water Resources Technical Publication, Revised Reprint, 1977.
2. Chow, Ven Te, Handbook of Applied Hydrology, McGraw - Hill Book Company, New York, 1964.
3. Chow, Ven Te, Open Channel Hydraulics, McGraw - Hill Book Company, New York, First Edition, 1959.
4. Commonwealth of Virginia, "Geologic Map of Virginia," Department of Conservation and Economic Development, and Division of Mineral Resources, 1963.
5. HR 33, "Seasonal Variations of Probable Maximum Precipitation, East of the 105th Meridian for Areas 10 to 1000 Square Miles and Durations of 6 to 48 Hours," (1956).
6. King, Horace Williams and Brater, Ernest F., Handbook of Hydraulics, Fifth Edition, McGraw - Hill Book Company, New York, 1963.
7. Soil Conservation Service, "National Engineering Handbook - Section 4, Hydrology," U.S. Department of Agriculture, 1964.
8. Soil Conservation Service, "National Engineering Handbook - Section 5, Hydraulics," U.S. Department of Agriculture.
9. U.S. Army, Hydrologic Engineering Center, "Flood Hydrograph Package (HEC-1), Dam Safety Investigations, Users Manual," Corps of Engineers, Davis, California, September 1978.
10. U.S. Army, Hydrologic Engineering Center, "HEC-2 Water Surface Profiles, Users Manual," Corps of Engineers, Davis, California, October 1973.
11. U.S. Army, "Inventory of United States Dams," Corps of Engineers, 9 September 1978.
12. U.S. Army, Office of the Chief of Engineers, "Appendix D, Recommended Guidelines for Safety Inspection of Dams," National Program of Inspection of Dams, Volume 1, Corps of Engineers, Washington, D.C., May 1975.

NAME OF DAM: SOUTH RIVER No. 6

VIII-1

AD-A084 373

BAKER (MICHAEL) JR INC BEAVER PA
NATIONAL DAM SAFETY PROGRAM. SOUTH RIVER NUMBER 6 (ID VA-01509)--ETC(U)
FEB 80 J A WALSH

F/6 13/13

DACW65-78-D-0016

NL

UNCLASSIFIED

2 - 2

DATE

6 80

END

DATE

6 80

DTIC

13. U.S. Army, Office of the Chief of Engineers, Engineering Circular EC-1110-2-163 (Draft Engineering Manual), "Spillway and Freeboard Requirements for Dams, Appendix C, Hydrometeorological Criteria and Hyetograph Estimates," (August 1975).
14. U.S. Army, Office of the Chief of Engineers, Engineering Circular EC-1110-2-188, "Engineering and Design, National Program of Inspection of Non-Federal Dams," Corps of Engineers, Washington, D.C., 30 December 1977.
15. U.S. Army, Office of the Chief of Engineers, Engineer Technical Letter No. ETL 1110-2-234, "Engineering and Design, National Program of Inspection of Non-Federal Dams, Review of Spillway Adequacy," Corps of Engineers, Washington, D.C., 10 May 1978.
16. U.S. Department of Commerce, "Technical Paper No. 40, Rainfall Frequency Atlas of the United States for Durations from 30 Minutes to 24 Hours and Return Periods from 1 to 100 Years," Weather Bureau, Washington, D.C., May 1961.
17. U.S. Department of Commerce, National Oceanic and Atmospheric Administration, "Hydrometeorological Report No. 51, Probable Maximum Precipitation Estimates, United States East of the 105th Meridian," Washington, D.C., June 1978.

NAME OF DAM: SOUTH RIVER No. 6

VIII-2